

SALES REPORT: CATERPILLAR 313GC - SN RHB20214 - Year 2022

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 313GC

Family: SMALL EXCAVATOR

Serial Number: RHB20214

Order Number MU/MM: MM00616332

Construction year: 2022

Hour meter: 803

General residual conditions Truck/Tyres: 60 %

Machine main application: Basic application

Location: CAGLIARI branch

Rating:

Public price: 111.500 €

MACHINE CONFIGURATION

Machine type Standard ● Boom type Mono boom ● Plant features Versatility ● Quick coupler Hydraulic ●
Bucket Standard ● Truck type Fixed ● Blade ● General Truck Residual 60% ● Cabin type Fixed standard ● Cabin fog Front superiore ● Air Conditioning system ● Product Link ● 13800 Kg ● CE Mark ● CE Certificate ● EPA Tag
Use and maintenance manual





MACHINE PHOTOS





















GENERAL APPEARANCE

Painting Conditions	Very Good
Counterweight conditions:	Very good
Frame/Bumper conditions:	Very Good
TRUCK	
Sprockets residual:	60
Front idler wheel residual:	60
Rollers upper/bottom residual:	60
♦ Chains residual:	60
Right side	
Door conditions (right):	Very good
♦ Spar conditions:	Very good



Left side

♦ Door conditions (left):	Very good
♦ Door conditions (left):	Very good
Spar conditions (left):	Very good
♦ Hood/Armor bottom conditions:	Present and intact

Functionality

Engine & electrical system functionality

In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
Engine working conditions:	Very good
Engine with oil leaks:	No
Engine presents blowby:	No
♦ Oil-Water presence:	No
Engine present smokiness:	No
Radiator conditions:	Very good
Starter motor conditions:	Very good
Batteries/Cables conditions:	Very good
Presence of electrical fault:	No

Functionality drive and rotation



Hydraulic pump conditions:	Very good
Engine rotation conditions:	Very good
Engine travel conditions:	Very good
Final drives conditions:	Very good
Hydraulic joint conditions:	Very good
	Presence of leaks : No
Hydraulic joint conditions:	Very good
	Presence of leaks : No
Linkage Group	
Hydraulic conditions linkage group:	No
▶ Boom structure:	Very good
	Presence of welding/cracks : No
Stick structure:	Very good
	Presence of welding/cracks : No
Flexible pipes conditions:	Very good
Boom cylinders conditions:	Very good
	Leaks : No
Stick cylinder conditions:	Very good
	Leaks : No
Bucket cylinder conditions:	Very good
	Leaks : No
Pins & Bushings boom conditions:	Very good
Pins & Bushings stick conditions:	Very good
Pins & Bushings bucket conditions:	Very good



Bucket & Get conditions:	Very good
Quick Coupler conditions:	Very good
Auto Lube working conditions:	No
Cabin and Tools	
Conditions internal cabin:	Very good
Flashing presents issues:	Yes
Lights & Windshield present issues:	Presents and functioning
Air conditioning is working:	Presente e funzionante
Back & side camera conditions:	Present and functioning
Check 81/2008	
Glass conditions:	Excellent - no needs repair
Lights conditions:	Excellent - no needs repair
Rear view mirrors conditions:	Excellent - no needs repair
Stepladders & handrails conditions:	Very good
Cameras conditions:	Excellent - no needs repair
Flashing conditions:	Present and functioning
Safety belt conditions:	Present and valid
Controls been modified:	No



Presence of Exclusion Control Lever:	Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	Yes
Batteries box shielded:	Yes
Acustic alarm works properly:	Yes
Boardwalk presence:	Present and functioning



Valutazione Macchina



Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.



Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.



La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.



Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.



Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating



Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.



Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.



Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.



Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.



Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components-with 70/80% of life residue. Machine in security conditions.