

## SALES REPORT: CATERPILLAR 323LN - SN KPE20366 - Year 2022

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 323LN

**Family:** MEDIUM EXCAVATOR

**Serial Number:** KPE20366

**Order Number MU/MM:** MM00637850

**Construction year:** 2022

**Hour meter:** 4558

**General residual conditions Truck/Tyres:** 1 %

**Machine main application:** Basic application

**Location:** AREZZO branch

**Rating:** ★★★☆☆

**Public price:** 127.000 €

#### MACHINE CONFIGURATION

---


- Machine type Standard • Boom type Mono boom • Boom check valves • Stick check valves • Plant features Versatility
- Quick coupler Hydraulic • Bucket Standard • Truck type Fixed • Blade • General Truck Residual 1%
- Cabin type Fixed standard • Cabin fog Front superiore • Air Conditioning system • Auto Lube system • Product Link • Antitheft alarm • 1 Kg • CE Mark • CE Certificate • EPA Tag • Use and maintenance manual

## MACHINE PHOTOS

---







## GENERAL APPEARANCE

---

---

◆ Painting Conditions	Very Good
◆ Counterweight conditions:	Very good
◆ Frame/Bumper conditions:	Very Good

---

## TRUCK

---

◆ Sprockets residual:	1
◆ Front idler wheel residual:	1
◆ Rollers upper/bottom residual:	1
◆ Chains residual:	1

---

## Right side

---

◆ Door conditions (right):	Very good
◆ Spar conditions:	Very good

---

## Left side

---

◆ Door conditions (left):	Very good
◆ Door conditions (left):	Very good
◆ Spar conditions (left):	Very good
◆ Hood/Armor bottom conditions:	Present and intact

---

## Functionality

---

## Engine & electrical system functionality

---

- ◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"
- ◆ Engine working conditions: Very good
- ◆ Engine with oil leaks: No
- ◆ Engine presents blowby: No
- ◆ Oil-Water presence: No
- ◆ Engine present smokiness: No
- ◆ Radiator conditions: Very good
- ◆ Starter motor conditions: Very good
- ◆ Batteries/Cables conditions: Very good
- ◆ Presence of electrical fault: No

---

## Functionality drive and rotation

---

- ◆ Hydraulic pump conditions: Very good
- ◆ Engine rotation conditions: Very good
- ◆ Engine travel conditions: Very good
- ◆ Final drives conditions: Very good
- ◆ Hydraulic joint conditions: Very good

Presence of leaks : No

- ◆ Hydraulic joint conditions: Very good

Presence of leaks : No

---

## Linkage Group

---

◆ Hydraulic conditions linkage group:	No
◆ Boom structure:	Very good
	Presence of welding/cracks : No
◆ Stick structure:	Very good
	Presence of welding/cracks : No
◆ Flexible pipes conditions:	Very good
◆ Boom cylinders conditions:	Very good
	Leaks : No
◆ Stick cylinder conditions:	Very good
	Leaks : No
◆ Bucket cylinder conditions:	Very good
	Leaks : No
◆ Pins & Bushings boom conditions:	Very good
◆ Pins & Bushings stick conditions:	Very good
◆ Pins & Bushings bucket conditions:	Very good
◆ Bucket & Get conditions:	Very good
◆ Quick Coupler conditions:	Very good
◆ Auto Lube working conditions:	No

---

## Cabin and Tools

---

◆ Conditions internal cabin:	Very good
------------------------------	-----------

◆ Flashing presents issues:	Yes
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning is working:	Presente e funzionante
◆ Back & side camera conditions:	Present and functioning

### Check 81/2008

---

◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Rear view mirrors conditions:	Excellent - no needs repair
◆ Stepladders & handrails conditions:	Very good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning



## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components with 70/80% of life residue. Machine in security conditions.