

## SALES REPORT: CATERPILLAR 914M - SN H2400346 - Year 2017

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 914M

**Family:** SMALL WHEEL LOADER

**Serial Number:** H2400346

**Order Number MU/MM:** MU00580013

**Construction year:** 2017

**Hour meter:** 8035

**General residual conditions Truck/Tyres:** 100 %

**Machine main application:** Industry - not corrosive field

**Location:** SZ SERVICE DI STEFANO ZUIN branch

**Rating:** ★★★★★☆

**Public price:** 80.000 €

#### MACHINE CONFIGURATION

---

● Machine type Standard - GP ● Steering type Command steering ● Differential Type Standard ● Transmission type Automatic ● Ride Control ● Auxiliary Systems ● Quick Coupler System ● Quick coupler Hydraulic Attacco Rapido ISO ● Bucket Ditch Cleaning Bucket . Get Cover Blade Benna elevato ribaltamento doppio pistone ● Tyres type Standard ● General Tyres Residual 100 Triangle La macchina verrà fornita con 4 gomme nuove 100% da piazzale Triangle NO GOMME IN FOTO ● Rops Close ● Cabin fog Front ● Air Conditioning system ● Auto Lube system ● CE Mark ● CE Certificate ● Registration book & Licence plate undefined Macchina estera senza omologazione stradale ● EPA Family Code: HPKXL04.4MT1

**MACHINE PHOTOS**

◆ Il contaore e':

Funzionante



**GENERAL APPEARANCE**

◆ Painting Conditions:

Good

◆ Counterweight conditions:

Good

Needs painting? : Yes

◆ Frame/Bumper conditions:

Good

---

◆ Door conditions:	Good
◆ Central joint:	Good
◆ Fender/Mudguard conditions:	Excellent
◆ Other notes: Macchina proveniente da industria necessita ritocchi di verniciatura soprattutto sulla parte frontale / assale anteriore	

---

### Tyres

---

◆ Front Tyres residual:	100
◆ Front Tyres residual:	100

---

### Functionality

---

#### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
◆ Engine working conditions:	Very good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good
◆ Batteries/Cables conditions:	Good

---

◆ Presence of electrical fault: No

---

### Functionality drive and rotation

---

◆ Hydraulic pump conditions: Good

---

◆ Engine travel conditions: Good

---

◆ Final drives conditions: Good

---

◆ Hydraulic joint conditions: Good

Presence of leaks : No

---

◆ Gear switches go/back conditions: Very Good

---

### Engine & electrical system functionality

---

◆ Engine working conditions: Good

---

◆ Radiator conditions: Good

---

◆ Starter motor conditions: Good

---

### Linkage Group

---

◆ Tenuta idraulica braccio (il braccio cala): No

---

◆ Boom structure: Good

Presence of welding/cracks : No

---

◆ Flexible pipes conditions: Good

---

◆ Lifting cylinders conditions: Good

---

◆ Bucket cylinder conditions: Good

---

◆ Pins & Bushings bucket conditions:	Good
◆ Bucket & Get conditions:	Good
◆ Quick Coupler conditions:	Good
◆ Funzionamento Impianto Ingrassaggio Automatico:	Sì
◆ Annotazioni su:	Due piccole saldature da riprendere sulla benna

### Cabin and Tools

---

◆ Conditions internal cabin:	Very good
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air contidioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Present and functioning

### Check 81/2008

---

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Very good
◆ Cameras conditions:	Excellent - no needs repair

◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and expired
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.