

SALES REPORT: CATERPILLAR 352F - SN KBP00259 - Year 2015

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 352F

Family: MEDIUM EXCAVATOR

Serial Number: KBP00259

Order Number MU/MM: MU00745913

Construction year: 2015

Hour meter: 12118

General residual conditions Truck/Tyres: 50 %

Machine main application: Basic application

Location: Stock CATANIA

Rating:

Public price: Ask

MACHINE CONFIGURATION

Machine type Standard ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Hammer line ● Quick coupler Hydraulic ● Bucket Standard 1800mm Get Teeth ● Truck type Mechanic extendible
General Truck Residual 50% ● Cabin type Fixed standard ● Cabin fog Front superiore ● Air Conditioning system ● Product Link ● 51700 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● FCPXL12.5HTF EPA





MACHINE PHOTOS

♦ Il contaore è: Funzionante























































Functionality

| Painting Conditions | Good |
|--------------------------------|------|
| Counterweight conditions: | Good |
| Frame/Bumper conditions: | Good |
| TRUCK | |
| > Sprockets residual: | 60 |
| Front idler wheel residual: | 60 |
| Rollers upper/bottom residual: | 60 |
| Chains residual: | 40 |
| Right side | |
| Door conditions (right): | Good |
| > Spar conditions: | Good |
| Left side | |
| Door conditions (left): | Good |
| Door conditions (left): | Good |
| Spar conditions (left): | Good |
| | |



Engine & electrical system functionality

| In quale stato è stata visionata la macchina: | Accesa e funzionante "al lavoro" |
|---|----------------------------------|
| Engine working conditions: | Very good |
| Engine with oil leaks: | No |
| Engine presents blowby: | No |
| Oil-Water presence: | No |
| Engine present smokiness: | No |
| Radiator conditions: | Very good |
| Starter motor conditions: | Very good |
| Batteries/Cables conditions: | Very good |
| Presence of electrical fault: | No |
| Functionality drive and rotation | |
| Hydraulic pump conditions: | Very good |
| Engine rotation conditions: | Very good |
| Engine travel conditions: | Very good |
| Final drives conditions: | Good |
| Hydraulic joint conditions: | Good |
| | Presence of leaks : No |
| Hydraulic joint conditions: | Good |
| | Presence of leaks : No |



Linkage Group

| • | Hydraulic conditions linkage group: | No |
|----------|-------------------------------------|---------------------------------|
| • | Boom structure: | Good |
| | | Presence of welding/cracks : No |
| • | Stick structure: | Good |
| | | Presence of welding/cracks : No |
| • | Flexible pipes conditions: | Good |
| • | Boom cylinders conditions: | Good |
| | | Leaks : No |
| • | Stick cylinder conditions: | Good |
| | | Leaks : No |
| • | Bucket cylinder conditions: | Good |
| | | Leaks : No |
| \ | Pins & Bushings boom conditions: | Good |
| ♦ | Pins & Bushings stick conditions: | Good |
| • | Pins & Bushings bucket conditions: | Good |
| • | Bucket & Get conditions: | Good |
| • | Quick Coupler conditions: | Good |
| • | Auto Lube working conditions: | No |
| | | |

Cabin and Tools

♦ Conditions internal cabin: Good



| Flashing presents issues: | Yes |
|-------------------------------------|--------------------------|
| Lights & Windshield present issues: | Presents and functioning |
| Air conditioning is working: | Presente e funzionante |
| Back & side camera conditions: | Present and functioning |
| | |

Check 81/2008

Boardwalk presence:

| Glass conditions: | Excellent - no needs repair |
|--|-----------------------------|
| → Lights conditions: | Excellent - no needs repair |
| Rear view mirrors conditions: | Excellent - no needs repair |
| Stepladders & handrails conditions: | Good |
| Cameras conditions: | Excellent - no needs repair |
| Flashing conditions: | Present and functioning |
| Safety belt conditions: | Present and valid |
| → Controls been modified: | No |
| Presence of Exclusion Control Lever: | Yes |
| ♦ Are Tools Functional & Visible with tag: | Yes |
| Canopy completed and comes with keys and bolt: | Yes |
| All Pipes with no damage e/o scratches: | Yes |
| Batteries box shielded: | Yes |
| Acustic alarm works properly: | No |

Present and functioning





Valutazione Macchina



Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.



Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.



La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.



Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.



Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating



Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.



Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.



Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.



Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.



Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components-with 70/80% of life residue. Machine in security conditions.