

SALES REPORT: DOOSAN - DAEWOO DX530 - SN 1010### - Year 2022

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: DX530

Family: MEDIUM EXCAVATOR

Serial Number: 1010###

Order Number MU/MM: MU00752174

Construction year: 2022

Hour meter: 2470

General residual conditions Truck/Tyres: 70 %

Machine main application: Basic application

Machine availability date: 01/12/2024

Location: Coming in

Rating:

Public price: Ask

MACHINE CONFIGURATION

• Machine type Standard • Boom type Mono boom • Boom check valves • Stick check valves • Plant features Hammer line impianto dedicato all'attacco rapido • Quick coupler Hydraulic GEITH attacco attrezzatura interasse tra perni 590mm larghezza int. 470mm diametro perni 120mm • Bucket Heavy duty 1600 Get undefined • Truck type Mechanic extendible • General Truck Residual 70% • Cabin type Fixed standard • Cabin fog Upper • Air Conditioning system • Auto Lube system • 52700 Kg • CE Mark • CE Certificate • Use and maintenance manual • AVAILABLE FROM MARCH 2025





MACHINE PHOTOS

♦ Il contaore è: Funzionante





























GENERAL APPEARANCE

Painting Conditions	Very Good
Counterweight conditions:	Very good
Frame/Bumper conditions:	Very Good
TRUCK	
Sprockets residual:	70
Front idler wheel residual:	70
Rollers upper/bottom residual:	70
♦ Chains residual:	70
Right side	
Door conditions (right):	Very good
Spar conditions:	Very good
Left side	
Door conditions (left):	Very good
Door conditions (left):	Very good
Spar conditions (left):	Very good
Hood/Armor bottom conditions:	Present and intact



Hydraulic joint conditions:

Engine & electrical system functionality

In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
Engine working conditions:	Very good
Engine with oil leaks:	No
Engine presents blowby:	No
Oil-Water presence:	No
Engine present smokiness:	No
Radiator conditions:	Very good
Starter motor conditions:	Very good
Batteries/Cables conditions:	Very good
Presence of electrical fault:	No
Functionality drive and rotation	
Hydraulic pump conditions:	Very good
Engine rotation conditions:	Very good
Engine travel conditions:	Very good
Final drives conditions:	Very good
Hydraulic joint conditions:	Very good
	Presence of leaks : No

Very good



Linkage Group

Hydraulic conditions linkage group:	No
♦ Boom structure:	Very good
	Presence of welding/cracks : No
♦ Stick structure:	Very good
	Presence of welding/cracks : No
→ Flexible pipes conditions:	Very good
Boom cylinders conditions:	Very good
	Leaks : No
Stick cylinder conditions:	Very good
	Leaks : No
Bucket cylinder conditions:	Very good
	Leaks : No
Pins & Bushings boom conditions:	Very good
Pins & Bushings stick conditions:	Very good
Pins & Bushings bucket conditions:	Very good
Bucket & Get conditions:	Very good
Quick Coupler conditions:	Very good
Auto Lube working conditions:	SI

Cabin and Tools

Conditions internal cabin:



All Pipes with no damage e/o scratches:

Batteries box shielded:

Flashing presents issues:	No
Lights & Windshield present issues:	Presents and functioning
Air conditioning is working:	Presente e funzionante
Back & side camera conditions:	Present and functioning
Annotazioni su:	telecamera 360°
Check 81/2008	
Glass conditions:	Excellent - no needs repair
Lights conditions:	Excellent - no needs repair
Rear view mirrors conditions:	Excellent - no needs repair
Stepladders & handrails conditions:	Very good
Cameras conditions:	Excellent - no needs repair
Flashing conditions:	Not functioning
Safety belt conditions:	Present and valid
Controls been modified:	No
Presence of Exclusion Control Lever:	Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes

Yes

Yes



Acustic alarm works properly:

♦ Boardwalk presence: Present and functioning

Yes



Valutazione Macchina



Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.



Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.



La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.



Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.



Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating



Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.



Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.



Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.



Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.



Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components-with 70/80% of life residue. Machine in security conditions.