

SALES REPORT: MANITOU MT1335H - SN 1002133 - Year 2018

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: MT1335H

Family: FIXED TELESCOPIC HANDLER

Serial Number: 1002133

Order Number MU/MM: MU00762348

Construction year: 2018

Hour meter: 3782

General residual conditions Truck/Tyres: 30 %

Machine main application: Basic application

Location: Stock Officina 51

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

• Machine type Standard - GP • Boom type Mono boom • Boom check valves • undefined • Tyres type undefined • Stabilizers 2 Stabilizers • Auxiliary Systems • Bucket Standard Get Cover Blade • Forks • Tyres type Standard • General Tyres Residual 30 • Rops Close • 9230 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate

MACHINE PHOTOS

◆ Il contaore e':

Funzionante







GENERAL APPEARANCE

- ◆ Painting Conditions: Good

- ◆ Counterweight conditions: Poor
Needs painting? : Yes

- ◆ Frame/Bumper conditions: Good

- ◆ Door conditions: Good

- ◆ Fender/Mudguard conditions: Good

Tyres

- ◆ Front Tyres residual: 30

- ◆ Front Tyres residual: 30

Functionality

Engine & electrical system functionality

- ◆ In quale stato è stata visionata la macchina:
 Accesa e provata per ispezione

- ◆ Engine working conditions:
 Good

- ◆ Engine with oil leaks:
 No

- ◆ Engine presents blowby:
 No

- ◆ Oil-Water presence:
 No

- ◆ Engine present smokiness:
 No

- ◆ Radiator conditions:
 Good

- ◆ Starter motor conditions:
 Good

- ◆ Batteries/Cables conditions:
 Good

- ◆ Presence of electrical fault:
 No

Functionality drive and rotation

- ◆ Hydraulic pump conditions:
 Good

- ◆ Engine travel conditions:
 Good

- ◆ Final drives conditions:
 Good

- ◆ Hydraulic joint conditions:
 Good

- ◆ Gear switches go/back conditions:
 Good

Presence of leaks : No

Engine & electrical system functionality

◆ Engine working conditions: Good

◆ Radiator conditions: Good

Linkage Group

◆ Tenuta idraulica braccio (il braccio cala): No

◆ Boom structure: Good

Photos

Presence of welding/cracks : No



◆ Flexible pipes conditions: Good

◆ Lifting cylinders conditions: Good

◆ Bucket cylinder conditions: Very good

◆ Pins & Bushings bucket conditions: Good

◆ Bucket & Get conditions: Good

◆ Quick Coupler conditions: NA - Not applicable

◆ Funzionamento Impianto Ingrassaggio Automatico: No

Cabin and Tools

- ◆ Conditions internal cabin: Good

- ◆ Lights & Windshield present issues: Presents and functioning

- ◆ Air conditioning & Filters conditions: Non Presente

- ◆ Back & side camera conditions: Not functioning

Check 81/2008

- ◆ Condizioni freni: Buono

- ◆ Condizioni freno di Stazionamento: Buono

- ◆ Glass conditions: Excellent - no needs repair

- ◆ Lights conditions: Excellent - no needs repair

- ◆ Condizioni specchietti: Eccellente - non necessita riparazione

- ◆ Stepladders & handrails conditions: Good

- ◆ Cameras conditions: Broken or Chipped - needs repair

- ◆ Flashing conditions: Not functioning

- ◆ Safety belt conditions: Present and valid

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes

- ◆ Are Tools Functional & Visible with tag: Yes

- ◆ Canopy completed and comes with keys and bolt: Yes



◆ All Pipes with no damage e/o scratches: Yes

◆ Batteries box shielded: Yes

◆ Acoustic alarm works properly: Yes

◆ Boardwalk presence: Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.