

## SALES REPORT: CATERPILLAR 914 - SN JC300687 - Year 2022

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** 914

**Family:** SMALL WHEEL LOADER

**Serial Number:** JC300687

**Order Number MU/MM:** MU00767700

**Construction year:** 2022

**Hour meter:** 6128

**General residual conditions Truck/Tyres:** 20 %

**Machine main application:** Landfill, Industry - not corrosive field

**Location:** Stock ROMA

**Rating:** ★★☆☆☆

**Public price:** 64.500 €

### MACHINE CONFIGURATION

---

● Machine type Standard - GP ● Steering type Command steering Presence of Command Steering No ● Differential Type Standard ● Transmission type Hydrostatic ● Ride Control ● Auxiliary Systems ● Quick Coupler System SENZA BENNA ● Tyres type Rock ● General Tyres Residual 20 17.5R25 Aeolus ● Rops Close ● Air Conditioning system ● Product Link ● 8660 Kg ● CE Mark ● CE Certificate ● MPKXL03.6FX1-030 EPA ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate TARGA IN POSSESSO DEL CLIENTE

**MACHINE PHOTOS**

---

◆ Il contaore e':

Funzionante





**GENERAL APPEARANCE**

◆ Painting Conditions: Poor

---

◆ Counterweight conditions: Good

Needs painting? : Yes

---

◆ Frame/Bumper conditions: NA - Not Applicable

---

◆ Door conditions: Good

---

◆ Central joint: Good

---

◆ Fender/Mudguard conditions: Poor

---

◆ Other notes: Segni strusciature su carrozzeria e su contrappeso;

---

## Tyres

---

◆ Front Tyres residual: 20

---

◆ Front Tyres residual: 20

---

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"

---

◆ Engine working conditions: Good

---

◆ Engine with oil leaks: No

If Yes, where : No perdite visive

---

◆ Engine presents blowby: No

---

◆ Oil-Water presence: No

---

- ◆ Engine present smokiness: No

---

- ◆ Radiator conditions: Good

---

- ◆ Starter motor conditions: Good

---

- ◆ Batteries/Cables conditions: Good

---

- ◆ Presence of electrical fault: No

---

### Functionality drive and rotation

---

- ◆ Hydraulic pump conditions: Good

---

- ◆ Engine travel conditions: Good

---

- ◆ Final drives conditions: Good

---

- ◆ Hydraulic joint conditions: NA - Not applicable  
Presence of leaks : No

---

- ◆ Gear switches go/back conditions: Good

---

### Engine & electrical system functionality

---

- ◆ Engine working conditions: Good

---

- ◆ Radiator conditions: Good

---

- ◆ Starter motor conditions: Good

---

### Linkage Group

---

- ◆ Tenuta idraulica braccio (il braccio cala): No

---

- ◆ Boom structure: Good

Presence of welding/cracks : No

◆ Flexible pipes conditions:	Poor
◆ Lifting cylinders conditions:	Good
◆ Bucket cylinder conditions:	Good
◆ Pins & Bushings bucket conditions:	Good
◆ Bucket & Get conditions:	NA - Not applicable
◆ Quick Coupler conditions:	NA - Not applicable
◆ Funzionamento Impianto Ingrassaggio Automatico:	No

### Cabin and Tools

◆ Conditions internal cabin:	Good
	Other notes : Cuscino rotto del sedile
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Present and functioning
◆ Annotazioni su:	Qualche copri fanalino rotto

### Check 81/2008

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions:	Excellent - no needs repair

◆ Lights conditions:	Broken or Chipped - needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Poor
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Not present

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.