

**SALES REPORT: CATERPILLAR 323LN - SN KPE00### - Year 2020**

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

**GENERAL CONDITIONS**

---

**MACHINE DATA**

---

**Model:** 323LN**Family:** MEDIUM EXCAVATOR**Serial Number:** KPE00###**Order Number MU/MM:** MU00811726**Construction year:** 2020**Hour meter:** 3400**General residual conditions Truck/Tyres:** 80 %**Machine main application:** Basic application**Machine availability date :** 27/02/2026**Location:** Coming in**Rating:** ★★★☆☆**Public price:** 145.000 €**MACHINE CONFIGURATION**

---

- Machine type Standard • Boom type Mono boom • Boom check valves • Stick check valves • Plant features Versatility • Quick coupler Hydraulic Cat CW40S • Bucket Standard 1400 Get Teeth • Truck type Fixed • General Truck Residual 80% • Cabin type Fixed standard • Cabin fog Front superiore • Air Conditioning system
- Product Link • 23000 Kg • CE Mark • CE Certificate • Use and maintenance manual

**CGT S.p.A. - A TESYA COMPANY**

Direzione Generale: Via Padana Superiore, 19 - 20055 Vimodrone - Milano  
tel. +39 02 27427.1 - fax +39 02 27427.554 - Numero Verde 800.827.134 - [www.cgt.it](http://www.cgt.it)

Sede legale e domicilio fiscale: Via Torino, 45 - 13100 Vercelli - Capitale sociale in Euro 20.640.000 interamente versato

Camera di Commercio Monte Rosa, Laghi, Alto Piemonte - R.E.A. n. 155698

Registro Imprese, Codice Fiscale e Partita IVA n. 01674190028 - Società soggetta a direzione e coordinamento socio unico TESYA S.p.A.




## MACHINE PHOTOS


---

◆ Il contatore è:

Funzionante









## GENERAL APPEARANCE

---

◆ Painting Conditions	Very Good
◆ Counterweight conditions:	Very good
◆ Frame/Bumper conditions:	Very Good

## TRUCK

---

◆ Sprockets residual:	80
◆ Front idler wheel residual:	80
◆ Rollers upper/bottom residual:	80
◆ Chains residual:	80

## Right side

---

- ◆ Door conditions (right): Very good
- ◆ Spar conditions: Very good

---

## Left side

---

- ◆ Door conditions (left): Very good
- ◆ Door conditions (left): Very good
- ◆ Spar conditions (left): Very good
- ◆ Hood/Armor bottom conditions: Present and intact

---

## Functionality

---

### Engine & electrical system functionality

---

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione
- ◆ Engine working conditions: Excellent
- ◆ Engine with oil leaks: No
- ◆ Engine presents blowby: No
- ◆ Oil-Water presence: No
- ◆ Engine present smokiness: No
- ◆ Radiator conditions: Very good
- ◆ Starter motor conditions: Very good

---

◆ Batteries/Cables conditions: Very good

---

◆ Presence of electrical fault: No

---

### Functionality drive and rotation

---

◆ Hydraulic pump conditions: Very good

---

◆ Engine rotation conditions: Very good

---

◆ Engine travel conditions: Very good

---

◆ Final drives conditions: Very good

---

◆ Hydraulic joint conditions: Very good

Presence of leaks : No

---

◆ Hydraulic joint conditions: Very good

Presence of leaks : No

---

### Linkage Group

---

◆ Hydraulic conditions linkage group: No

---

◆ Boom structure: Very good

Presence of welding/cracks : No

---

◆ Stick structure: Very good

Presence of welding/cracks : No

---

◆ Flexible pipes conditions: Very good

---

◆ Boom cylinders conditions: Good

Leaks : No

---

◆ Stick cylinder conditions: Good

Leaks : No

---

◆ Bucket cylinder conditions:	Good
	Leaks : No
◆ Pins & Bushings boom conditions:	Good
◆ Pins & Bushings stick conditions:	Good
◆ Pins & Bushings bucket conditions:	Good
◆ Bucket & Get conditions:	Good
◆ Quick Coupler conditions:	Good
◆ Auto Lube working conditions:	No

## Cabin and Tools

---

◆ Conditions internal cabin:	Very good
◆ Flashing presents issues:	No
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning is working:	Presente e funzionante
◆ Back & side camera conditions:	Present and functioning

## Check 81/2008

---

◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Rear view mirrors conditions:	Excellent - no needs repair
◆ Stepladders & handrails conditions:	Good

◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acustic alarm works properly:	No
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components with 70/80% of life residue. Machine in security conditions.