SALES REPORT: CATERPILLAR MH3024 - SN FB700814 - Year 2021

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: MH3024

Family: WHEEL EXCAVATOR

Serial Number: FB700814

Order Number MU/MM: MM00512012

Construction year: 2021

Hour meter: 9965

General residual conditions Truck/Tyres: 60 %

Machine main application: Basic application

Location: MILANO branch

Rating: ★★★☆☆

Public price: 190.000 €

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Versatility ● Quick coupler Hydraulic ● Bucket / Grapple Standard ● Tyres type Twin Wheel ● General Tyres Residual 60 - - ● Blade ● Stabilizers 4 Stabilizers ● Cabin type Fixed standard ● Cabin fog Front superiore ● Air Conditioning system Operation Yes Operation No ● Product Link ● Antitheft alarm ● 23000 Kg ● CE Mark ● CE Certificate ● KPKXL07.0BN1 EPA ● Use and maintenance manual ● Registration book & Licence plate No Registration book & Licence plate

MACHINE PHOTOS

































GENERAL APPEARANCE

Painting Conditions	Very Good
Counterweight conditions	Very good
	Needs painting? : No
Frame / Bumper conditions	Very Good

Tyres

Front Tyres residual	60
Front Tyres residual	60

Right side

Door conditions (right)	Very good
Spar conditions (right)	Very good

Left side

Door conditions (left)	Very good
Door conditions (left)	Very good
Spar conditions (left)	Very good
Hood / Armor bottom conditions	Present and intact

Functionality

Engine & electrical system functionality

In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
Engine functionality conditions	Very good
Engine with oil leaks	No
Engine presents blowby	No
Oil-Water presence	No

Engine present smokiness	No
Radiator conditions	Very good
Starter motor conditions	Very good
Batteries/Cables conditions	Very good
Presence of electrical fault	No

Functionality drive and rotation

Hydraulic pump conditions	Very good
Engine rotation conditions	Very good
Engine travel conditions	Very good
Final drives conditions	Very good
Hydraulic joint conditions	Very good Presence of leaks : No
Hydraulic joint conditions	Very good Presence of leaks : No
Tenuta idraulica braccio (il braccio cala):	No

Linkage Group

Hydraulic conditions linkage group (Boom is lowering?)	No
Boom structure	Very good Presence of welding/cracks : No
Stick structure	Very good Presence of welding/cracks : No

Flexible pipes conditions	Very good
Boom cylinders conditions	Very good Leaks : No
Stick cylinder conditions	Very good Leaks : No
Bucket / Grapple cylinder conditions	Very good Leaks : No
Pins & Bushings boom conditions	Very good
Pins & Bushings stick conditions	Very good
Pins & Bushings bucket conditions	Very good
Bucket / Grapple & Get conditions	Very good
Quick Coupler conditions	Very good
Funzionamento Impianto Ingrassaggio Automatico:	Sì

Cabin and Tools

Conditions internal cabin	Very good
Flashing presents issues	Yes
Lights & Windshield present issues	Presents and functioning
Air contidioning & Filters conditions	Presents and functioning
Back & side camera conditions	Present and functioning

Check 81/2008

Condizioni freni:	Molto Buono
Condizioni freno di stazionamento:	Molto Buono
Glass conditions	Excellent - no needs repair
Lights conditions	Excellent - no needs repair
Rear view mirrors conditions	Excellent - no needs repair
Stepladders & handrails conditions	Very good
Cameras conditions	Excellent - no needs repair
Flashing conditions	Present and functioning
Safety belt conditions	Present and valid
Controls been modified	No
Presence of Exclusion Control Lever	Yes
Are Tools Functional & Visible with tag	Yes
Canopy completed and comes with keys and bolt	Yes
All Pipes with no damage e/o scratches	Yes
Batteries box shielded	Yes
Acustic alarm works properly	Yes
Boardwalk presence	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components-with 70/80% of life residue. Machine in security conditions.