SALES REPORT: SANDVIK QI341 - SN QI341-10### - Year 2017

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: QI341

Family: CRUSHERS

Serial Number: QI341-10###

Order Number MU/MM: MU00685697

Construction year: 2017

Hour meter: 3749

General residual conditions Truck/Tyres: %

Machine main application:

Location: Coming in

Rating: ★★★☆☆

Public price: 417.000 €

MACHINE CONFIGURATION

● Machine type Mass Excavator ● undefined ● ● Boom type ● Boom check valves ● Plant features ● undefined ● CE Mark ● CE Certificate ● Use and maintenance manual

ORIGINS & APPLICATION

- Machine Origins: Consignment

MACHINE PHOTOS

- Il contaore e': Funzionante
































SANDVIK
CE
Mfg Year
2017
Type
Maximum Operating Speed RPM
Nominal Power (kW)
Serial No.
Order No.
Engine No.
Manufacturing No.
Mass Kg
SANDVIK
2017 MODEL
COMMISSIONING DATE
DEALER/DISTRIBUTOR
ENZIONE
UNZIONARE LA
JI SERVOSOSTEGNI
12-55-0295 IT




CAT
CATERPILLAR INC.
EMISSION CONTROL INFORMATION
D9N04612
ENGINE FAMILY: DCPXL09.3HPA
DISPLACEMENT: 9.3
DATE OF MANUFACTURE: NOV 2013


CAT
CATERPILLAR INC.
EMISSION CONTROL INFORMATION
D9N04612
ENGINE FAMILY: DCPXL09.3HPA
DISPLACEMENT: 9.3
DATE OF MANUFACTURE: NOV 2013


SANDVIK
CE
Mfg Year
Type
Maximum Operating Speed RPM
Nominal Power (kW)
Serial No.
Order No.
Engine No.
Manufacturing No.
Mass Kg
SANDVIK
2017 MODEL
COMMISSIONING DATE
DEALER/DISTRIBUTOR
TENZIONE
FUNZIONARE LA
JI SERVOSOSTEGNI
12-55-0295 rl













SANDVIK MOBILES


SANDVIK MOBILES











GENERAL APPEARANCE

- Painting Conditions — Poor

FRANTOIO

- Spar conditions: — Good
- Alimentatore: — Buono

Bocca del frantoio:	Buono
Usura mascelle:	50
Usura corazze	60
Scarico sotto frantoio:	Buono

NASTRI

Nastro principale (tappeto,raschiatori,rulli):	Buono
Nastro laterale scarto:	Buono
Deferrizzatore:	Buono
Sistema abbattimento polveri:	Buono

CARRO

Condizioni generali carro	Buono

Functionality

In quale stato è stata visionata la macchina:	Accesa e provata per ispezione

Engine & electrical system functionality

Engine working conditions:	Good
Engine with oil leaks:	No
Engine presents blowby:	No

Engine present smokiness:	No
Radiator conditions:	Good
Starter motor conditions:	Good
Batteries/Cables conditions:	Good
Presence of electrical fault:	Non presente

Functionality drive and rotation

Hydraulic pump conditions:	Good
Engine travel conditions:	Good

Linkage Group

Boom structure:	Good
Stick structure:	Good

Check 81/2008

Lights conditions:	Excellent - no needs repair
Condizioni specchietti:	Eccellente - non necessita riparazione
Stepladders & handrails conditions:	Good
Cameras conditions:	Broken or Chipped - needs repair
Flashing conditions:	Not functioning
Controls been modified:	No

Presence of Exclusion Control Lever:	Yes
	If No, are control levers protected to accidental funcionality? : Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	Yes
Batteries box shielded:	Yes
Acustic alarm works properly:	Yes
Boardwalk presence:	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components-with 70/80% of life residue. Machine in security conditions.