SALES REPORT: CATERPILLAR MH3024 - SN FB700629 - Year 2019

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: MH3024

Family: WHEEL EXCAVATOR

Serial Number: FB700629

Order Number MU/MM: MU00726837

Construction year: 2019

Hour meter: 12381

General residual conditions Truck/Tyres: 80 %

Machine main application: Industry - not corrosive field

Location: Stock Milano Usato

Rating: ★★★☆☆

Public price: 90.000 €

MACHINE CONFIGURATION

● Machine type Material Handling MH ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Versatility ● Tyres type Twin Wheel ● General Tyres Residual 80 ● Blade ● Stabilizers 4 Stabilizers ● Cabin type Hydraulic lift ● Cabin fog Front superiore ● Air Conditioning system ● Auto lube system ● Product Link ● 22000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate No Registration book & Licence plate ● EPA Family Number: KPKXL07.0BN1

MACHINE PHOTOS

- Il contaore e': Funzionante






























MODEL MH3024
BUILD 06C
CAT
CATERPILLAR
CATMH302CFB700629
CATERPILLAR INC.
PEORIA, IL 61629
USA
MADE IN FRANCE
OF DOMESTIC AND
FOREIGN COMPONENTS
ISSUE 1


CAT














MODEL MH3024
BUILD 06C
CAT
CATERPILLAR
PRODUCT IDENTIFICATION NUMBER
CATMH302CFB700629
CATERPILLAR INC.
PEORIA, IL 61629
USA
MADE IN FRANCE
OF DOMESTIC AND
FOREIGN COMPONENTS
ISSUE 1


11854 h
1
Active Tool





GENERAL APPEARANCE

Painting Conditions	Good
Counterweight conditions	Poor
	Needs painting? : Yes
Frame / Bumper conditions	Good

Tyres

N/D	80
N/D	80

Right side

N/D	Good

N/D	Good

Left side

N/D	Good
N/D	Good
N/D	Good
Hood / Armor bottom conditions	Present and bash

Functionality

Engine & electrical system functionality

N/D	Accesa e funzionante "al lavoro"
N/D	Very good
N/D	No
N/D	No
N/D	No
N/D	No
N/D	Good
N/D	Good
N/D	Good
N/D	No

Functionality drive and rotation

N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	Good Presence of leaks : No
N/D	Good Presence of leaks : No
N/D	No

Linkage Group

N/D	No
N/D	Good Presence of welding/cracks : No
N/D	Good Presence of welding/cracks : No
N/D	Good
N/D	Good Leaks : No
N/D	Good Leaks : No
N/D	Good

	Leaks : No
N/D	Good
N/D	Good
N/D	Good
N/D	NA - Not applicable
N/D	NA - Not applicable
N/D	Sì

Cabin and Tools

Conditions internal cabin	Good
Flashing presents issues	No
Lights & Windshield present issues	Presents and functioning
Air contidioning & Filters conditions	Presents and functioning
Back & side camera conditions	Present and functioning

Check 81/2008

Condizioni freni:	Buono
Condizioni freno di Stazionamento:	Buono
Glass conditions	Excellent - no needs repair
Lights conditions	Excellent - no needs repair
Rear view mirrors conditions	Excellent - no needs repair

Stepladders & handrails conditions	Good
Cameras conditions	Excellent - no needs repair
Flashing conditions	Not functioning
Safety belt conditions	Present and valid
Controls been modified	No
Presence of Exclusion Control Lever	Yes
	If No, are control levers protected to accidental funcionality? : Yes
Are Tools Functional & Visible with tag	Yes
Canopy completed and comes with keys and bolt	No
All Pipes with no damage e/o scratches	Yes
Batteries box shielded	Yes
Acustic alarm works properly	Yes
Boardwalk presence	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.