SALES REPORT: TEREX TM350#KTERE - SN 350M301365 - Year 2008

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: TM350#KTERE

Family: WHEEL EXCAVATOR

Serial Number: 350M301365

Order Number MU/MM: MU00736176

Construction year: 2008

Hour meter: 19866

General residual conditions Truck/Tyres: 50 %

Machine main application: Heavy application

Location: Stock CAGLIARI

Rating: ★★★☆☆

Public price: 22.000 €

MACHINE CONFIGURATION

● Machine type Material Handling MH ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Versatility ● Bucket / Grapple Grapple ● Tyres type Twin Wheel ● General Tyres Residual 50 12.00.20 SOLIDEAL ● Stabilizers 4 Stabilizers ● Cabin type Hydraulic lift ● Air Conditioning system Operation Yes Operation Yes ● 35000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate No Registration book & Licence plate

MACHINE PHOTOS









TEREX

















DEUTZ
DEUTZ AG










ATLAS


Hersteller:
Producer:
TEREX GmbH
27777 Ganderkesee Germany
Fahrzeugtyp:
Type of vehicle:
TM350
Baujahr:
Year of construction:
2008
Fahrzeug-Ident.Nr.:
Vehicle-ident.No.:
350M301365
zul. Gesamtgew.:
Admissible total weight:
33500
kg
zul. Achslast, vorn:
Admissible front axle load:
kg
zul. Achslast, hinten:
Admissible rear axle load:
kg
Motortyp / -Leistung:
Type of Engine / power:
TCD2013L062V/166
KW
TEREX


h





GENERAL APPEARANCE

Painting Conditions	Poor
Counterweight conditions	Good
	Needs painting? : No
Frame / Bumper conditions	Good

Tyres

N/D	50
N/D	50

Right side

N/D	NA - Not applicable
N/D	Good

Left side

N/D	Good
N/D	Good
N/D	Good
Hood / Armor bottom conditions	Present and intact

Functionality

Engine & electrical system functionality

N/D	Accesa e funzionante "al lavoro"
N/D	Poor
N/D	Yes
	If Yes, where : servocomandi - pistoni sollevamento+stick

N/D	No
N/D	No
N/D	No
N/D	Good
N/D	Good
N/D	Good
N/D	No

Functionality drive and rotation

N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	Poor Presence of leaks : Yes
N/D	Good Presence of leaks : Yes
N/D	No

Linkage Group

N/D	Yes
N/D	Good

	Presence of welding/cracks : No
N/D	Good
	Presence of welding/cracks : No
N/D	Good
N/D	Poor
	Leaks : Yes
N/D	Poor
	Leaks : Yes
N/D	Poor
	Leaks : Yes
N/D	Good
N/D	Good
N/D	Poor
N/D	Good
N/D	NA - Not applicable
N/D	No

Cabin and Tools

Conditions internal cabin	Good
Flashing presents issues	Yes
Lights & Windshield present issues	Presents and functioning
Air contidioning & Filters conditions	Presents and functioning
Back & side camera conditions	Not functioning

Check 81/2008

Condizioni freni:	Buono
Condizioni freno di Stazionamento:	Buono
Glass conditions	Excellent - no needs repair
Lights conditions	Excellent - no needs repair
Rear view mirrors conditions	Excellent - no needs repair
Stepladders & handrails conditions	Good
Cameras conditions	Broken or Chipped - needs repair
Flashing conditions	Not functioning
Safety belt conditions	Present and expired
Controls been modified	No
Presence of Exclusion Control Lever	Yes
Are Tools Functional & Visible with tag	Yes
Canopy completed and comes with keys and bolt	Yes
All Pipes with no damage e/o scratches	Yes
Batteries box shielded	Yes
Acustic alarm works properly	Yes
Boardwalk presence	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.