SALES REPORT: BITELLI BB632 - SN 130000843 - Year 2000

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: BB632

Family: ASPHALT PAVERS

Serial Number: 130000843

Order Number MU/MM: MU00780237

Construction year: 2000

Hour meter: 8214

General residual conditions Truck/Tyres: %

Machine main application:

Location: Stock Padova

Rating: ★★★☆☆

Public price: 9.500 €

MACHINE CONFIGURATION

● Machine type Mass Excavator ● Boom type ● Boom check valves ● Plant features ● Truck type ● Product Link undefined non girevoli ● 6150 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS


















È VIETATO SOSTARE
NEL RAGGIO D'AZIONE
DELLA MACCHINA









84


CAT
17




84




CE
BITELLI
Via IV Novembre, 2 MINERBIO-BO-ITALIA
DGM. OL 91029 MOBO
COEFF. DI ASSORB. CORRETTO 0,9
MACCHINA MODELLO
MACHINE MODEL
BB 632
N° MATRICOLA
SERIAL NUMBER
000843
TIPO
TYPE
BB 130
POTENZA
ENGINE POWER
kW
38
giri/1'
rpm
2600
MASSA COMPLESSIVA kg
OVERALL MASS
6150
ANNO DI FABBRICAZIONE
PRODUCTION YEAR
2000
SFORZO AMMISSIBILE AL GANCIO TRAINO N
MAX PULL ON THE TOWING HOOK
24600
Cod. 774444
BITELLI
ASSICURAZIONE QUALITÀ
DELIBERATO







GENERAL APPEARANCE

Painting Conditions	Good
Spar conditions:	Good
Residual % - Tyres/Track:	70
Residual % - Cushion:	10
Seat condition:	Not working
Engine working conditions:	Poor
Radiator conditions:	Poor
Batteries/Cables conditions:	Good

Functionality

SCREED

Hydraulic pump conditions:	1
Brakes and steering clutch conditions:	20
Engine travel conditions:	20
Final drives conditions:	50
Residuo % Nastri:	50
Residuo % Fondi	50
Apertura massima Allargamenti (se presenti):	non presenti

Engine & electrical system functionality

In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
Engine working conditions:	Excellent
Engine with oil leaks:	No
Engine presents blowby:	No
Engine present smokiness:	No
Radiator conditions:	Very good
Starter motor conditions:	Excellent
Batteries/Cables conditions:	Excellent
Presence of electrical fault:	No

Functionality drive and rotation

Hydraulic pump conditions:	Good
Engine travel conditions:	Good
Final drives conditions:	Good

Linkage Group

Boom structure:	Good
	Presenza di perdite? Se si, specificare da dove: : no
Stick structure:	Good
	Presenza di perdite? Se si, specificare da dove: : no
Flexible pipes conditions:	Good
	Presenza di perdite? Se si, specificare da dove: : no
Boom cylinders conditions:	Good

Check 81/2008

Condizioni freni:	Molto Buono
Condizioni freno di Stazionamento:	Molto Buono
Lights conditions:	Broken or Chipped - needs repair
Condizioni specchietti:	Rotto o Scheggiato - necessita riparazione
Stepladders & handrails conditions:	Good
Cameras conditions:	Broken or Chipped - needs repair
Flashing conditions:	Not functioning
Controls been modified:	No
Presence of Exclusion Control Lever:	No
	If No, are control levers protected to accidental funcionality? : Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	Yes
Batteries box shielded:	Yes
Acustic alarm works properly:	No
Boardwalk presence:	Present and bashee

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.