SALES REPORT: CASE 921#KCASE - SN N7F201373 - Year 2007

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 921#KCASE

Family: MEDIUM WHEEL LOADER

Serial Number: N7F201373

Order Number MU/MM: MU00787462

Construction year: 2007

Hour meter: 11300

General residual conditions Truck/Tyres: 20 %

Machine main application: Basic application

Location: Stock CATANIA

Rating: ★★★☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard - GP ● Steering type Command steering ● Differential Type Standard ● Transmission type Manual ● Bucket Standard 3000 mm Get Teeth ● Tyres type Standard ● General Tyres Residual 20 26.5 Triangle ● Rops Close ● Air Conditioning system ● 24000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate undefined

MACHINE PHOTOS

- Il contaore e': Funzionante










921E




921F























CASE
CASE







GENERAL APPEARANCE

Painting Conditions:	Poor
Counterweight conditions:	Good
	Needs painting? : Yes
Frame/Bumper conditions:	Good
Door conditions:	Good
Central joint:	Good
Fender/Mudguard conditions:	Good

Tyres

Front Tyres residual:	20
Front Tyres residual:	20

Functionality

Engine & electrical system functionality

In quale stato è stata visionata la macchina:	Accesa e provata per ispezione

Engine working conditions:	Good
Engine with oil leaks:	No
Engine presents blowby:	No
Oil-Water presence:	No
Engine present smokiness:	No
Radiator conditions:	Poor
Starter motor conditions:	Good
Batteries/Cables conditions:	Good
Presence of electrical fault:	No

Functionality drive and rotation

Hydraulic pump conditions:	Good
Engine travel conditions:	NA - Not applicable
Final drives conditions:	Poor
Hydraulic joint conditions:	Good Presence of leaks : No
Gear switches go/back conditions:	Good

Engine & electrical system functionality

Engine working conditions:	Good
Radiator conditions:	Poor
Starter motor conditions:	Good

Linkage Group

Tenuta idraulica braccio (il braccio cala):	No
Boom structure:	Good
	Presence of welding/cracks : No
Flexible pipes conditions:	Good
Lifting cylinders conditions:	Good
Bucket cylinder conditions:	Good
Pins & Bushings bucket conditions:	Good
Bucket & Get conditions:	Poor
Quick Coupler conditions:	NA - Not applicable
Funzionamento Impianto Ingrassaggio Automatico:	No

Cabin and Tools

Conditions internal cabin:	Good
Lights & Windshield present issues:	Present and not functioning
Air contidioning & Filters conditions:	Present and not functioning
Back & side camera conditions:	Present and not functioning

Check 81/2008

Condizioni freni:	Buono

Condizioni freno di Stazionamento:	Buono
Glass conditions:	Broken or Chipped - needs repair
Lights conditions:	Broken or Chipped - needs repair
Condizioni specchietti:	Rotto o Scheggiato - necessita riparazione
Stepladders & handrails conditions:	Good
Cameras conditions:	Broken or Chipped - needs repair
Flashing conditions:	Not functioning
Safety belt conditions:	Present and expired
Controls been modified:	No
Presence of Exclusion Control Lever:	Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	No
Batteries box shielded:	Yes
Acustic alarm works properly:	No
Boardwalk presence:	Not present

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.