SALES REPORT: CATERPILLAR 432 - SN H7E01### - Year 2022

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 432

Family: BACKHOE LOADER

Serial Number: H7E01###

Order Number MU/MM: MU00844948

Construction year: 2022

Hour meter: 2360

General residual conditions Truck/Tyres: %

Machine main application: Basic application

Machine availability date : 31/12/2026

Location: Coming in


Rating: ★★★☆☆


Public price: Ask

MACHINE CONFIGURATION


● Steering type Command steering ● Rops Close ● Transmission type Hydrostatic ● Tyres type ● ● Ride Control ● Quick coupler Hydraulic ● Bucket Rock/Stone 1 MQ. NESSUNA BENNA ULTERIORE ● Differential Type Self-Locking ● Auxiliary Systems IMPIANTO COMBINATO ● Quick coupler Hydraulic CR 70 CANGINI ● Bucket Standard 0,2 MQ. N. 3 BENNE ● Air Conditioning system ● Product Link ● 8322 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate AMS086


MACHINE PHOTOS


















432



32
CGT
A TESYA COMPANY





103


CAT
CGT
A TESYA COMPANY


CAT
IVECO


CAT
CGT
A TESYA COMPANY


CAT


CAT








MODEL 432
BUILD 07A
CAT00432TH7E01345
MODEL NUMBER
SERIAL NUMBER
ARRANGEMENT NUMBER
CAT
CATERPILLAR
dB


N
05:29PM
2359.7
24%
67%



GENERAL APPEARANCE

Painting Conditions:	Good
Frame/Bumper conditions:	Good
Door conditions:	Good
Fender/Mudguard conditions:	Good

Tyres

N/D	80
N/D	80

Functionality

Engine & electrical system functionality

N/D	Spenta e ferma
N/D	Good
N/D	No
N/D	No
N/D	No
N/D	No
N/D	Good
N/D	Good
N/D	Good
N/D	Non Presente

Functionality drive and rotation

N/D	Good
N/D	Good
N/D	Good Presence of leaks : No
N/D	Good
N/D	NA - Non Applicabile

Linkage Group

N/D	No
N/D	Good Presence of welding/cracks : No
N/D	Good
N/D	Good Leaks : No
N/D	Good Leaks : No
N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	No

Linkage Group

N/D	No
N/D	Buono
N/D	Good Presence of welding/cracks : No
N/D	Good
N/D	Good Leaks : No
N/D	Buono

N/D	Good
	Leaks : No
N/D	Good
N/D	Buono
N/D	Good
N/D	Good
N/D	Good
N/D	No

Cabin and Tools

Conditions internal cabin:	Good
Lights & Windshield present issues:	Presents and functioning
Air contidioning & Filters conditions:	Presents and functioning

Check 81/2008

Condizioni freni:	Buono
Condizioni freno di Stazionamento:	Buono
Glass conditions:	Excellent - no needs repair
Lights conditions:	Excellent - no needs repair
Condizioni specchietti:	Eccellente - non necessita riparazione
Stepladders & handrails conditions:	Good

Cameras conditions:	Broken or Chipped - needs repair
Flashing conditions:	Present and functioning
Safety belt conditions:	Present and expired
Controls been modified:	No
Presence of Exclusion Control Lever:	Yes
	If No, are control levers protected to accidental funcionality? : Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	Yes
Batteries box shielded:	Yes
Acustic alarm works properly:	No
Boardwalk presence:	Not present

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.