SALES REPORT: CASE WX168#CASE - SN NZLB05005 - Year 2019

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: WX168#CASE

Family: WHEEL EXCAVATOR

Serial Number: NZLB05005

Order Number MU/MM: MU00845969

Construction year: 2019

Hour meter: 4476

General residual conditions Truck/Tyres: 30 %

Machine main application: Basic application

Location: Stock CAGLIARI

Rating: ★★★☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Triple boom ● Boom check valves ● Stick check valves ● Plant features Versatility linea drenaggio impianto dedicato all'attacco rapido ● Quick coupler Hydraulic case ● Bucket / Grapple Standard Get Get Get Cleat 1000 una benna ● Tyres type Twin Wheel ● General Tyres Residual 30 10.00.20 gemellari marangoni post sn 60 % le altre CAMSO 30% ● Blade ● Stabilizers 2 Stabilizers ● Cabin type Fixed standard ● Air Conditioning system Operation Yes ● 16000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate AK A285

MACHINE PHOTOS

- Il contaore e': Funzionante








Scavi F.lli Argiolas
CASE
40





















CASE













CNH Industrial Italia S.p.A.
MADE IN ITALY
WX168
CASE
CONSTRUCTION
CNH Industrial Italia S.p.A.
kg
kg
kg
kg
kW


ORE DI FUNZION.
TOTALE 04476
ATTIVITA 00632
set









GENERAL APPEARANCE

Painting Conditions	Poor
Counterweight conditions	Good
	Needs painting? : No
Frame / Bumper conditions	Good

Tyres

N/D	40
N/D	40

Right side

N/D	Good

N/D	Good
N/D	molta ruggine su cofano motore e sup. cabina

Left side

N/D	Good
N/D	Good
N/D	Good
Hood / Armor bottom conditions	Present and intact

Functionality

Engine & electrical system functionality

N/D	Accesa e provata per ispezione
N/D	Good
N/D	No
N/D	No
N/D	No
N/D	No
N/D	Good
N/D	Good
N/D	Good

N/D	Sì
	If present, add details : selettore regime motore da sostituire gia' ordinato

Functionality drive and rotation

N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	Good
	Presence of leaks : No
N/D	Good
	Presence of leaks : No
N/D	No

Linkage Group

N/D	Yes
N/D	Good
	Presence of welding/cracks : No
N/D	Good
	Presence of welding/cracks : No
N/D	Good
N/D	Good
	Leaks : No
N/D	Good
	Leaks : No

N/D	Good
	Leaks : No
N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	No
N/D	lieve gioco boccola benna

Cabin and Tools

Conditions internal cabin	Good
	Other notes : manca visore telecamera su leva escusione comandi molla di ritorno da riparare
Flashing presents issues	Yes
Lights & Windshield present issues	Presents and functioning
Air contidioning & Filters conditions	Presents and functioning
Back & side camera conditions	Present and not functioning

Check 81/2008

Condizioni freni:	Molto Buono
Condizioni freno di Stazionamento:	Buono
Glass conditions	Broken or Chipped - needs repair

Lights conditions	Excellent - no needs repair
Rear view mirrors conditions	Excellent - no needs repair
Stepladders & handrails conditions	Poor
Cameras conditions	Broken or Chipped - needs repair
Flashing conditions	Present and functioning
Safety belt conditions	Present and expired
Controls been modified	No
Presence of Exclusion Control Lever	Yes
	If No, are control levers protected to accidental funcionality? : No
Are Tools Functional & Visible with tag	Yes
Canopy completed and comes with keys and bolt	Yes
All Pipes with no damage e/o scratches	Yes
Batteries box shielded	Yes
Acustic alarm works properly	Yes
Boardwalk presence	Present and functioning
Annotazioni su	una scatta da addrizzare

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.