

## SALES REPORT: CATERPILLAR DPC13 - SN NH300647 - Year 2015

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** DPC13

**Family:** POWER SYSTEM

**Serial Number:** NH300647

**Order Number MU/MM:** EU00745029

**Construction year:** 2015

**Hour meter:** 11637

**General residual conditions Truck/Tyres:** %

**Machine main application:** Heavy application

**Location:** Stock BARI

**Rating:** ★★☆☆☆

**Public price:** 20.000 €

#### MACHINE CONFIGURATION

---

● Machine type Standard ● ● Boom type ● Stick check valves ● Boom check valves ● Truck type undefined ● ● kW 368 kVA 400 - kW 320 kVA 450 - kW 360 ● 4667 Kg ● ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS

---

◆ Il contaore è:

Funzionante

◆ Annotazioni sul:

MOTORE DA REVISIONARE - GRUPPO ELETTROGENO PRESSO NOSTRA OFFICINA DI MODUGNO (BA)

---







Galaxy A52  
11:14



Galaxy A52  
11:15



Galaxy A52  
11:13



Galaxy A52  
11:13

**GENERAL APPEARANCE**

◆ Painting Conditions	Good
◆ Frame/Bumper conditions:	Good
◆ Door conditions (right):	Good
◆ Condizione Cablaggi:	Buono

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina:	Spenta e ferma
◆ Engine working conditions:	Not working
◆ Engine with oil leaks:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Hydraulic pump conditions:	Good
◆ Starter motor conditions:	Good
◆ Door conditions (left):	Good
◆ Spar conditions (left):	Good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	Not present

### GENERATORE

- 
- ◆ Condizioni alternatore: Buono

---

  - ◆ Condizioni magneto termico di controllo: Buono

---

  - ◆ Condizioni Cablaggi Buono

---

### Functionality drive and rotation

---

- ◆ Final drives conditions: Good

---

- ◆ Hydraulic joint conditions: Good

---

- ◆ Engine presents blowby: Buono

---

### Check 81/2008

---

- ◆ Cameras conditions: Excellent - no needs repair

---

- ◆ Safety belt conditions: Not present/Broken

---

- ◆ Controls been modified: No

---

- ◆ Are Tools Functional & Visible with tag: Yes

---

- ◆ Canopy completed and comes with keys and bolt: Yes

---

- ◆ All Pipes with no damage e/o scratches: Yes

---

- ◆ Batteries box shielded: Yes

---

- ◆ Boardwalk presence: Present and functioning

---

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.