

SALES REPORT: KOMPTECH HURRIKAN - SN 80217 - Year 2020

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: HURRIKAN

Family: SEPARATOR

Serial Number: 80217

Order Number MU/MM: MM00486260

Construction year: 2020

Hour meter: 1303

General residual conditions Truck/Tyres: %

Machine main application: Basic application

Location: Out for hire

Rating: ★★☆☆☆


Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard ● ● Plant features ● undefined ● 13000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS









GENERAL APPEARANCE

◆ Telaio:	Buono
◆ Painting Conditions	Good
◆ Tramoggia:	Buono

RETI

◆ Spar conditions:	Antintasante
	Conditiona : Good
<hr/>	
◆ Rete 2° piano:	Antintasante
	Condizioni : Buono
<hr/>	
◆ Rete 3° piano (se presente):	NA - Non Applicabile

NASTRI

◆ Nastro principale (tappeto,raschiatori,rulli):	Buono
<hr/>	
◆ Nastri laterali:	Buono
<hr/>	
◆ Deferrizzatore:	Buono
<hr/>	
◆ Sistema abbattimento polveri:	Buono

CARRO

◆ Condizioni generali carro	Buono
-----------------------------	-------

Functionality

◆ In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
---	----------------------------------

Engine & electrical system functionality

◆ Engine working conditions:	Good
<hr/>	
◆ Engine with oil leaks:	No
<hr/>	
◆ Engine presents blowby:	No

◆ Engine present smokiness: No

◆ Radiator conditions: Good

◆ Starter motor conditions: Good

◆ Batteries/Cables conditions: Good

◆ Presence of electrical fault: Not present

Functionality drive and rotation

◆ Hydraulic pump conditions: Good

◆ Engine travel conditions: Good

Linkage Group

◆ Boom structure: Good

Presenza di perdite? Se si, specificare da dove: -

◆ Stick structure: Good

Presenza di perdite? Se si, specificare da dove: -

Check 81/2008

◆ Lights conditions: Excellent - no needs repair

◆ Condizioni specchietti: Eccellente - non necessita riparazione

◆ Stepladders & handrails conditions: Good

◆ Cameras conditions: Excellent - no needs repair

◆ Flashing conditions: Present and functioning

◆ Controls been modified:	No
---------------------------	----

◆ Presence of Exclusion Control Lever:	Yes
If No, are control levers protected to accidental functionality? : Yes	

◆ Are Tools Functional & Visible with tag:	Yes
--	-----

◆ Canopy completed and comes with keys and bolt:	Yes
--	-----

◆ All Pipes with no damage e/o scratches:	Yes
---	-----

◆ Batteries box shielded:	Yes
---------------------------	-----

◆ Acustic alarm works properly:	Yes
---------------------------------	-----

◆ Boardwalk presence:	Present and functioning
-----------------------	-------------------------

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.