

SALES REPORT: CATERPILLAR 330 GC - SN SCZ20032 - Year 2021

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 330 GC

Family: MEDIUM EXCAVATOR

Serial Number: SCZ20032

Order Number MU/MM: MM00517295

Construction year: 2021

Hour meter: 5338

General residual conditions Truck/Tyres: 60 %

Machine main application: Basic application

Location: AREZZO branch

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

- Machine type Standard
- Boom type Mono boom
- Boom check valves
- Stick check valves
- Plant features Versatility
- Quick coupler Mechanic
- Bucket Standard
- Truck type Fixed
- General Truck Residual 60%
- Cabin type Fixed standard
- Cabin fog Front superiore
- Air Conditioning system
- Product Link
- Antitheft alarm
- 29800 Kg
- CE Mark
- CE Certificate
- EPA Tag
- Use and maintenance manual

MACHINE PHOTOS





GENERAL APPEARANCE

- ◆ Painting Conditions Very Good

- ◆ Counterweight conditions: Very good

- ◆ Frame/Bumper conditions: Very Good

TRUCK

- ◆ Sprockets residual: 60

- ◆ Front idler wheel residual: 60

- ◆ Rollers upper/bottom residual: 60

- ◆ Chains residual: 60

Right side

- ◆ Door conditions (right): Very good
 - ◆ Spar conditions: Very good
-

Left side

- ◆ Door conditions (left): Very good
 - ◆ Door conditions (left): Very good
 - ◆ Spar conditions (left): Very good
 - ◆ Hood/Armor bottom conditions: Present and intact
-

Functionality

Engine & electrical system functionality

- ◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"
- ◆ Engine working conditions: Very good
- ◆ Engine with oil leaks: No
- ◆ Engine presents blowby: No
- ◆ Oil-Water presence: No
- ◆ Engine present smokiness: No
- ◆ Radiator conditions: Very good
- ◆ Starter motor conditions: Very good

◆ Batteries/Cables conditions: Very good

◆ Presence of electrical fault: No

Functionality drive and rotation

◆ Hydraulic pump conditions: Very good

◆ Engine rotation conditions: Very good

◆ Engine travel conditions: Very good

◆ Final drives conditions: Very good

◆ Hydraulic joint conditions: Very good

Presence of leaks : No

◆ Hydraulic joint conditions: Very good

Presence of leaks : No

Linkage Group

◆ Hydraulic conditions linkage group: No

◆ Boom structure: Very good

Presence of welding/cracks : No

◆ Stick structure: Very good

Presence of welding/cracks : No

◆ Flexible pipes conditions: Very good

◆ Boom cylinders conditions: Very good

Leaks : No

◆ Stick cylinder conditions: Very good

Leaks : No



◆ Bucket cylinder conditions:	Very good
	Leaks : No
◆ Pins & Bushings boom conditions:	Very good
◆ Pins & Bushings stick conditions:	Very good
◆ Pins & Bushings bucket conditions:	Very good
◆ Bucket & Get conditions:	Very good
◆ Quick Coupler conditions:	Very good
◆ Auto Lube working conditions:	No

Cabin and Tools

◆ Conditions internal cabin:	Very good
◆ Flashing presents issues:	Yes
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning is working:	Presente e funzionante
◆ Back & side camera conditions:	Present and functioning

Check 81/2008

◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Rear view mirrors conditions:	Excellent - no needs repair
◆ Stepladders & handrails conditions:	Very good



◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.