

**SALES REPORT: CATERPILLAR 330 NG - SN XNB20172 - Year 2022**

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

**GENERAL CONDITIONS**

---

**MACHINE DATA**

---

**Model:** 330 NG

**Family:** MEDIUM EXCAVATOR

**Serial Number:** XNB20172

**Order Number MU/MM:** MM00589589

**Construction year:** 2022

**Hour meter:** 472

**General residual conditions Truck/Tyres:** 60 %

**Machine main application:** Basic application

**Location:** Out for hire

**Rating:** ★★★☆☆

**Public price:** 265.000 €

**MACHINE CONFIGURATION**

---

- Machine type Standard
- Boom type Mono boom
- Boom check valves
- Stick check valves
- Plant features Versatility
- Quick coupler Hydraulic
- Bucket Standard
- Truck type Fixed
- General Truck Residual 60%
- Cabin type Fixed standard
- Cabin fog Front superiore
- Air Conditioning system
- Product Link
- 30000 Kg
- CE Mark
- CE Certificate
- EPA Tag
- Use and maintenance manual

## MACHINE PHOTOS

---

FOTO IN AGGIORNAMENTO



## GENERAL APPEARANCE

---

◆ Painting Conditions	Good
◆ Counterweight conditions:	Good
◆ Frame/Bumper conditions:	Good

## TRUCK

---

◆ Sprockets residual:	60
◆ Front idler wheel residual:	60
◆ Rollers upper/bottom residual:	60
◆ Chains residual:	60

## Right side

---

◆ Door conditions (right):	Good
----------------------------	------

---

◆ Spar conditions: Good

---

## Left side

---

◆ Door conditions (left): Good

---

◆ Door conditions (left): Good

---

◆ Spar conditions (left): Good

---

◆ Other notes

---

◆ Hood/Armor bottom conditions: Present and intact

---

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"

---

◆ Engine working conditions: Good

---

◆ Engine with oil leaks: No

---

◆ Engine presents blowby: No

---

◆ Oil-Water presence: No

---

◆ Engine present smokiness: No

---

◆ Radiator conditions: Good

---

◆ Starter motor conditions: Good

---

◆ Batteries/Cables conditions: Good

---

◆ Presence of electrical fault: No

---

### Functionality drive and rotation

---

◆ Hydraulic pump conditions: Good

---

◆ Engine rotation conditions: Good

---

◆ Engine travel conditions: Good

---

◆ Final drives conditions: Good

---

◆ Hydraulic joint conditions: Good

Presence of leaks : No

---

◆ Hydraulic joint conditions: Good

Presence of leaks : No

---

### Linkage Group

---

◆ Hydraulic conditions linkage group: No

---

◆ Boom structure: Good

Presence of welding/cracks : No

---

◆ Stick structure: Good

Presence of welding/cracks : No

---

◆ Flexible pipes conditions: Good

---

◆ Boom cylinders conditions: Good

Leaks : No

---

◆ Stick cylinder conditions: Good

Leaks : No

---

◆ Bucket cylinder conditions: Good

Leaks : No

---

◆ Pins & Bushings boom conditions:	Good
◆ Pins & Bushings stick conditions:	Good
◆ Pins & Bushings bucket conditions:	Good
◆ Bucket & Get conditions:	Good
◆ Quick Coupler conditions:	Good
◆ Auto Lube working conditions:	No

## Cabin and Tools

---

◆ Conditions internal cabin:	Very good
◆ Flashing presents issues:	Yes
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning is working:	Presente e funzionante
◆ Back & side camera conditions:	Present and functioning

## Check 81/2008

---

◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Rear view mirrors conditions:	Excellent - no needs repair
◆ Stepladders & handrails conditions:	Very good
◆ Cameras conditions:	Excellent - no needs repair

◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components with 70/80% of life residue. Machine in security conditions.