

## SALES REPORT: KOMPTECH CR5200D - SN 447210 - Year 2022

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

### MACHINE DATA

---

**Model:** CR5200D

**Family:** SHREDDER

**Serial Number:** 447210

**Order Number MU/MM:** MM00595985

**Construction year:** 2022

**Hour meter:** 3911

**General residual conditions Truck/Tyres:** %

**Machine main application:**

**Location:** VERONA branch

**Rating:** ★★☆☆☆

**Public price:** 340.000 €

### MACHINE CONFIGURATION

---

● Machine type Long Reach ● undefined ● undefined ● undefined ● 27000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ●

## ORIGINS & APPLICATION

---

◆ Machine Origins:

Rental

## MACHINE PHOTOS

---









**GENERAL APPEARANCE**

◆ Painting Conditions

Good

## FRANTOIO

---

◆ Spar conditions:	Good
◆ Alimentatore:	Buono
◆ Bocca del frantoio:	Buono
◆ Usura mascelle:	-
◆ Usura corazze	-
◆ Scarico sotto frantoio:	Buono

## NASTRI

---

◆ Nastro principale (tappeto, raschiatori, rulli):	Buono
◆ Nastro laterale scarto:	Buono
◆ Deferrizzatore:	Buono
◆ Sistema abbattimento polveri:	Buono

## CARRO

---

◆ Condizioni generali carro	Buono
-----------------------------	-------

## Functionality

---

◆ In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
---	----------------------------------

## Engine & electrical system functionality

---

◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	Non presente

---

#### Functionality drive and rotation

---

◆ Hydraulic pump conditions:	Good
◆ Engine travel conditions:	Good

---

#### Linkage Group

---

◆ Boom structure:	Good
◆ Stick structure:	Good

---

#### Check 81/2008

---

◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione

---

◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	No
	If No, are control levers protected to accidental functionality? : No
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.