SALES REPORT: CATERPILLAR 908 - SN HZ800436 - Year 2023

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 908

Family: COMPACT WHEEL LOADER

Serial Number: HZ800436

Order Number MU/MM: MM00632304

Construction year: 2023

Hour meter: 9352

General residual conditions Truck/Tyres: 60 %

Machine main application: Basic application

Location: VILLA GIUSEPPE AUTOTRASPORTI branch

Rating: ★★★☆☆

Public price: 62.000 €

MACHINE CONFIGURATION

● Machine type Standard - GP ● Steering type Command steering ● Differential Type Standard ● Transmission type Automatic ● Bucket Standard ● Tyres type Standard ● General Tyres Residual 60 ● Rops Close ● Air Conditioning system ● Product Link ● 12000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate

MACHINE PHOTOS









GENERAL APPEARANCE

- Painting Conditions: Very Good

Counterweight conditions:	Very good
	Needs painting? : No
Frame/Bumper conditions:	Very Good
Door conditions:	Very good
Central joint:	Very good
Fender/Mudguard conditions:	Very good

Tyres

Front Tyres residual:	60
Front Tyres residual:	60

Functionality

Engine & electrical system functionality

In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
Engine working conditions:	Very good
Engine with oil leaks:	No
Engine presents blowby:	No
Oil-Water presence:	No
Engine present smokiness:	No
Radiator conditions:	Very good
Starter motor conditions:	Very good

- Batteries/Cables conditions: Very good
- Presence of electrical fault: No

Functionality drive and rotation

- Hydraulic pump conditions: Very good
- Engine travel conditions: Very good
- Final drives conditions: Very good
- Hydraulic joint conditions: Very good

  Presence of leaks : No
- Gear switches go/back conditions: Very Good

Engine & electrical system functionality

- Engine working conditions: Very good
- Radiator conditions: Very good
- Starter motor conditions: Very good

Linkage Group

- Tenuta idraulica braccio (il braccio cala): No
- Boom structure: Very good

  Presence of welding/cracks : No
- Flexible pipes conditions: Very good
- Lifting cylinders conditions: Very good

Bucket cylinder conditions:	Very good
Pins & Bushings bucket conditions:	Very good
Bucket & Get conditions:	Very good
Quick Coupler conditions:	Very good
Funzionamento Impianto Ingrassaggio Automatico:	Sì

Cabin and Tools

Conditions internal cabin:	Very good
Lights & Windshield present issues:	Presents and functioning
Air contidioning & Filters conditions:	Presents and functioning
Back & side camera conditions:	Present and functioning

Check 81/2008

Condizioni freni:	Molto Buono
Condizioni freno di stazionamento:	Molto Buono
Glass conditions:	Excellent - no needs repair
Lights conditions:	Excellent - no needs repair
Condizioni specchietti:	Eccellente - non necessita riparazione
Stepladders & handrails conditions:	Very good
Cameras conditions:	Excellent - no needs repair

Flashing conditions:	Present and functioning
Safety belt conditions:	Present and valid
Controls been modified:	No
Presence of Exclusion Control Lever:	Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	Yes
Batteries box shielded:	Yes
Acustic alarm works properly:	Yes
Boardwalk presence:	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.