

SALES REPORT: CATERPILLAR AP300F - SN FRA00229 - Year 2023

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: AP300F

Family: ASPHALT PAVERS

Serial Number: FRA00229

Order Number MU/MM: MM00658250

Construction year: 2023

Hour meter: 649

General residual conditions Truck/Tyres: %

Machine main application:

Location: Out for hire

Rating: ★★☆☆☆

Public price: 170.000 €

MACHINE CONFIGURATION

- Machine type Tyres • Screed Electric • Electric Burner Start • Track Type Rubber • Canopy • Traction (if Tyres) 6 x 4 • Bulkhead Heated girevoli • Leveling System Double Longitudinal ultrasound • 8000 Kg • CE Mark
- CE Certificate • Use and maintenance manual

MACHINE PHOTOS







GENERAL APPEARANCE

◆ Painting Conditions	Good
◆ Spar conditions:	Good
◆ Residual % - Tyres/Track:	60
◆ Residual % - Cushion:	60

◆ Seat condition:	Good
◆ Engine working conditions:	Good
◆ Radiator conditions:	Good
◆ Batteries/Cables conditions:	Good

Functionality

SCREED

◆ Hydraulic pump conditions:	-
◆ Brakes and steering clutch conditions:	60
◆ Engine travel conditions:	60
◆ Final drives conditions:	60
◆ Residuo % Nastri:	60
◆ Residuo % Fondi	60
◆ Apertura massima Allargamenti (se presenti):	-

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No

- ◆ Engine present smokiness: No

- ◆ Radiator conditions: Good

- ◆ Starter motor conditions: Good

- ◆ Batteries/Cables conditions: Good

- ◆ Presence of electrical fault: No

Functionality drive and rotation

- ◆ Hydraulic pump conditions: Good

- ◆ Engine travel conditions: Good

- ◆ Final drives conditions: Good

Linkage Group

- ◆ Boom structure: Good

- Presenza di perdite? Se si, specificare da dove: : -

- ◆ Stick structure: Good

- Presenza di perdite? Se si, specificare da dove: : -

- ◆ Flexible pipes conditions: Good

- Presenza di perdite? Se si, specificare da dove: : -

- ◆ Boom cylinders conditions: Good

Check 81/2008

- ◆ Condizioni freni: Buono

◆ Condizioni freno di Stazionamento:	Buono
◆ Lights conditions:	Excellent - no needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Very good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Present and functioning
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
	If No, are control levers protected to accidental functionality? : No
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.