**SALES REPORT: CATERPILLAR 950GC - SN M5T06596 - Year 2023**

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

## GENERAL CONDITIONS

### MACHINE DATA

**Model:** 950GC

**Family:** MEDIUM WHEEL LOADER

**Serial Number:** M5T06596

**Order Number MU/MM:** MM00679702

**Construction year:** 2023

**Hour meter:** 6572

**General residual conditions Truck/Tyres:** %

**Machine main application:** Basic application

**Location:** Out for hire

**Rating:** ★★★☆☆

**Public price:** 138.000 €

### MACHINE CONFIGURATION

● Machine type Standard - GP ● Steering type Command steering Presence of Command Steering No ● Differential Type Controlled Slippage ● Transmission type Automatic ● Ride Control ● Bucket Standard ● Tyres type Standard ● Rops Close ● Air Conditioning system ● Product Link ● 20000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate undefined● AVAILABLE FROM NOVEMBER

## MACHINE PHOTOS

## GENERAL APPEARANCE

| | |
|---|---|
| Painting Conditions: | Very Good |
| Counterweight conditions: | Very good |
| Frame/Bumper conditions: | Very Good |
| Door conditions: | Very good |
| Central joint: | Very good |
| Fender/Mudguard conditions: | Very good |

### Tyres

## Functionality

### Engine & electrical system functionality

| | |
|---|---|
| N/D | Accesa e funzionante "al lavoro" |
| N/D | Very good |
| N/D | No |
| N/D | No |
| N/D | No |

| | |
|---|---|
| N/D | No |
| N/D | Very good |
| N/D | Very good |
| N/D | Very good |
| N/D | No |

### Functionality drive and rotation

| | |
|---|---|
| N/D | Very good |
| N/D | Very good |
| N/D | Very good |
| N/D | Very good<br>Presence of leaks : No |
| N/D | Very Good |

### Engine & electrical system functionality

| | |
|---|---|
| N/D | Very good |
| N/D | Very good |
| N/D | Very good |

### Linkage Group

| | |
|---|---|
| N/D | No |
| N/D | Very good |

| | |
|---|---|
| | Presence of welding/cracks : No |
| N/D | Very good |
| N/D | Very good |
| N/D | Very good |
| N/D | Very good |
| N/D | Very good |
| N/D | Very good |
| N/D | Sì |

## Cabin and Tools

| | |
|---|---|
| Conditions internal cabin: | Very good |
| Lights & Windshield present issues: | Presents and functioning |
| Air contidioning & Filters conditions: | Presents and functioning |
| Back & side camera conditions: | Present and functioning |

## Check 81/2008

| | |
|---|---|
| Condizioni freni: | Molto Buono |
| Condizioni freno di stazionamento: | Molto Buono |
| Glass conditions: | Excellent - no needs repair |
| Lights conditions: | Excellent - no needs repair |

| | |
|---|---|
| Condizioni specchietti: | Eccellente - non necessita riparazione |
| Stepladders & handrails conditions: | Very good |
| Cameras conditions: | Excellent - no needs repair |
| Flashing conditions: | Present and functioning |
| Safety belt conditions: | Present and valid |
| Controls been modified: | No |
| Presence of Exclusion Control Lever: | Yes |
| Are Tools Functional & Visible with tag: | Yes |
| Canopy completed and comes with keys and bolt: | Yes |
| All Pipes with no damage e/o scratches: | Yes |
| Batteries box shielded: | Yes |
| Acustic alarm works properly: | Yes |
| Boardwalk presence: | Present and functioning |

# Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

# Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.