

SALES REPORT: RUBBLE MASTER HS3500M - SN HS3500M-96-05 - Year 2021

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: HS3500M

Family: SCREENING PLANTS

Serial Number: HS3500M-96-05

Order Number MU/MM: MU00616586

Construction year: 2021

Hour meter: 596

General residual conditions Truck/Tyres: %

Machine main application: Basic application

Location: VILLA GIUSEPPE AUTOTRASPORTI branch

Rating: ★★★★★

Public price: 160.000 €

MACHINE CONFIGURATION

● Machine type Mass Excavator ● ● ● 20000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS







GENERAL APPEARANCE

◆ Telaio:	Buono
◆ Painting Conditions	Good
◆ Tramoggia:	Buono

RETI

◆ Spar conditions:	Quadra Conditiona : Very good
◆ Rete 2° piano:	Quadra Condizioni : Molto Buono
◆ Rete 3° piano (se presente):	Quadra Condizioni : Molto Buono

NASTRI

◆ Nastro principale (tappeto, raschiatori, rulli):	Buono
◆ Nastri laterali:	Molto Buono

◆ Deferrizzatore: Molto Buono

◆ Sistema abbattimento polveri: Molto Buono

CARRO

◆ Condizioni generali carro Molto Buono

Functionality

◆ In quale stato è stata visionata la macchina: Accesa e funzionante "al lavoro"

Engine & electrical system functionality

◆ Engine working conditions: Very good

◆ Engine with oil leaks: No

◆ Engine presents blowby: No

◆ Engine present smokiness: No

◆ Radiator conditions: Good

◆ Starter motor conditions: Very good

◆ Batteries/Cables conditions: Very good

◆ Presence of electrical fault: Not present

Functionality drive and rotation

◆ Hydraulic pump conditions: Very good

◆ Engine travel conditions: Very good

Linkage Group

◆ Boom structure: Very good

Presenza di perdite? Se si, specificare da dove: : -

◆ Stick structure: Good

Presenza di perdite? Se si, specificare da dove: : -

Check 81/2008

◆ Lights conditions: Excellent - no needs repair

◆ Condizioni specchietti: Eccellente - non necessita riparazione

◆ Stepladders & handrails conditions: Excellent

◆ Cameras conditions: Excellent - no needs repair

◆ Flashing conditions: Present and functioning

◆ Controls been modified: No

◆ Presence of Exclusion Control Lever: No

If No, are control levers protected to accidental functionality? : Yes

◆ Are Tools Functional & Visible with tag: Yes

◆ Canopy completed and comes with keys and bolt: Yes

◆ All Pipes with no damage e/o scratches: Yes

◆ Batteries box shielded: Yes

◆ Acustic alarm works properly: Yes

◆ Boardwalk presence:

Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.