SALES REPORT: CATERPILLAR MH3024 - SN FB700436 - Year 2018

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: MH3024

Family: WHEEL EXCAVATOR

Serial Number: FB700436

Order Number MU/MM: MU00646591

Construction year: 2018

Hour meter: 8628

General residual conditions Truck/Tyres: 80 %

Machine main application: Industry - not corrosive field

Location: Stock Milano Usato

Rating: ★★★☆☆

Public price: 145.000 €

MACHINE CONFIGURATION

● Machine type Material Handling MH ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Versatility impianto dedicato all'attacco rapido L'attacco rapido che si vede in foto non verrà fornito . ● Tyres type Twin Wheel ● General Tyres Residual 80 Gomme piene Globe Star ● Stabilizers 4 Stabilizers ● Cabin type Hydraulic lift ● Air Conditioning system ● Auto lube system ● CE Mark ● CE Certificate ● EPA Family Code: JPKXL07.0BN1 ● Registration book & Licence plate No Registration book & Licence plate

MACHINE PHOTOS

- Il contaore e': Funzionante

















CAT
MH3024
33








MODEL NUMBER MH3024
CAT CATERPILLAR
CAT CATERPILLAR
PRODUCT IDENTIFICATION NUMBER *CATMH302CFB700436*
CATERPILLAR INC.
PEORIA, IL 61629
USA
MADE IN FRANCE
OF DOMESTIC AND
FOREIGN COMPONENTS
ISSUE 1




TO KOREA ONLY
4922233
X5020
EMISSION CONTROL INFORMATION
Peterborough, PE1 5FQ, United Kingdom
Engine Family: JPKXL07.0BN1
Displacement (L): 7.01
C7.1
THIS ENGINE COMPLIES WITH U.S EPA AND CALIFORNIA REGULATIONS FOR 2018 NONROAD DIESEL ENGINES AND U.S EPA REGULATIONS FOR 2018 STATIONARY DIESEL ENGINES
ULTRA LOW SULFUR FUEL ONLY
FEL (g/kWh)
NMHC: N/A
NOx: N/A
PM: 0.01
Emissions Control System
DOI,TAA,EGM,DOC,CTO,EGR
SCR,AMOX,EPR
Engine Type
130 < KW <= 560
Use Service tool to verify current engine settings
E11
120R-011033
STEP 4 FINAL
SEP 2018
X3397


15 35 8628 h
6
CAT
Servicestunden prüfen
CAT



GENERAL APPEARANCE

Painting Conditions	Very Good
Counterweight conditions	Very good
	Needs painting? : No
Frame / Bumper conditions	Very Good

Tyres

N/D	80
N/D	80

Right side

N/D	Very good

N/D	Very good

Left side

N/D	Very good
N/D	Very good
N/D	Very good
Hood / Armor bottom conditions	Present and intact

Functionality

Engine & electrical system functionality

N/D	Spenta e ferma
N/D	Good
N/D	No
N/D	No
N/D	No
N/D	No
N/D	Good
N/D	Good
N/D	Good
N/D	No

Functionality drive and rotation

N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	Good Presence of leaks : No
N/D	Good Presence of leaks : No
N/D	No

Linkage Group

N/D	No
N/D	Very good Presence of welding/cracks : No
N/D	Very good Presence of welding/cracks : No
N/D	Good
N/D	Good Leaks : No
N/D	Good Leaks : No
N/D	Good

	Leaks : No
N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	NA - Not applicable
N/D	Sì

Cabin and Tools

Conditions internal cabin	Good
Flashing presents issues	Yes
Lights & Windshield present issues	Presents and functioning
Air contidioning & Filters conditions	Presents and functioning
Back & side camera conditions	Present and functioning

Check 81/2008

Condizioni freni:	Buono
Condizioni freno di Stazionamento:	Buono
Glass conditions	Excellent - no needs repair
Lights conditions	Excellent - no needs repair
Rear view mirrors conditions	Excellent - no needs repair

Stepladders & handrails conditions	Good
Cameras conditions	Excellent - no needs repair
Flashing conditions	Present and functioning
Safety belt conditions	Present and valid
Controls been modified	No
Presence of Exclusion Control Lever	Yes
Are Tools Functional & Visible with tag	Yes
Canopy completed and comes with keys and bolt	Yes
All Pipes with no damage e/o scratches	Yes
Batteries box shielded	Yes
Acustic alarm works properly	Yes
Boardwalk presence	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.