

SALES REPORT: CATERPILLAR 730C2 - SN 2T400482 - Year 2017

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 730C2

Family: ARTICULATED TRUCKS

Serial Number: 2T400482

Order Number MU/MM: MU00669624

Construction year: 2017

Hour meter: 7847

General residual conditions Truck/Tyres: 60 %

Machine main application: Basic application

Location: MILANO branch

Rating: ★★☆☆☆

Public price: 220.000 €

MACHINE CONFIGURATION

• Body type Standard - GP • Tailgate • Rops Closed • Body • Differential Type Standard • Transmission type Automatic • Tyres type Standard • General Tyres Residual 60 - - • Air Conditioning system • Product Link • 23000 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate undefined

MACHINE PHOTOS







GENERAL APPEARANCE

◆ Painting Conditions:	Good
◆ Front axle conditions:	Good
◆ Rear axles conditions:	Good
◆ Frame/Bumper conditions:	Good
◆ Door conditions:	Good
◆ Cab/Canopy conditions:	Good
◆ Fender/Mudguard conditions:	Good

TYRES

◆ 1st Axle Tyres residual:	60
----------------------------	----

◆ Residual percentage	60
-----------------------	----

◆ 3rd Axle Tyres residual:	60
----------------------------	----

Functionality

Engine & electrical system functionality

◆ MACHINE STATUS DURING CHECK	Tuned on at work
-------------------------------	------------------

◆ Engine working conditions:	Good
------------------------------	------

◆ Engine with oil leaks:	No
--------------------------	----

◆ Engine presents blowby:	No
---------------------------	----

◆ Oil-Water presence:	No
-----------------------	----

◆ Engine present smokiness:	No
-----------------------------	----

◆ Radiator conditions:	Good
------------------------	------

◆ Starter motor conditions:	Good
-----------------------------	------

◆ Batteries/Cables conditions:	Good
--------------------------------	------

◆ Presence of electrical fault:	No
---------------------------------	----

Functionality drive and rotation

◆ Hydraulic pump conditions:	Good
------------------------------	------

◆ Engine travel conditions:	Good
-----------------------------	------

◆ Final drives conditions:	Good
----------------------------	------

◆ Hydraulic joint conditions:	Good
	Presence of leaks : No

◆ Gear switches go/back conditions:	Good
-------------------------------------	------

◆ Brakes conditions:	Good
----------------------	------

Cabin and Tools

◆ Conditions internal cabin:	Good
------------------------------	------

◆ Lights & Windshield present issues:	Presents and functioning
---------------------------------------	--------------------------

◆ Air conditioning & Filters conditions:	Presents and functioning
--	--------------------------

◆ Back & side camera conditions:	Present and functioning
----------------------------------	-------------------------

Check 81/2008

◆ Glass conditions:	Excellent - no needs repair
---------------------	-----------------------------

◆ Lights conditions:	Excellent - no needs repair
----------------------	-----------------------------

◆ Mirrors conditions:	Excellent - no reparation needed
-----------------------	----------------------------------

◆ Stepladders & handrails conditions:	Good
---------------------------------------	------

◆ Cameras conditions:	Excellent - no needs repair
-----------------------	-----------------------------

◆ Flashing conditions:	Present and functioning
------------------------	-------------------------

◆ Safety belt conditions:	Present and valid
---------------------------	-------------------

◆ Controls been modified:	No
---------------------------	----

◆ Presence of Exclusion Control Lever:	Yes
--	-----

◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.