SALES REPORT: CATERPILLAR PM200 - SN P1C00433 - Year 2009

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: PM200

Family: COLD PLANER

Serial Number: P1C00433

Order Number MU/MM: MU00728696

Construction year: 2009

Hour meter: 7612

General residual conditions Truck/Tyres: %

Machine main application:

Location: Stock Milano Usato

Rating: ★★★☆☆

Public price: 105.000 €

MACHINE CONFIGURATION

● Machine type Standard ● Boom type ● Plant features ● Truck type 10 ● Product Link 80 ● EPA Tag 80 ● 70 ● 32400 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS
































GENERAL APPEARANCE

Painting Conditions	Good
Spar conditions:	Good

Functionality

Engine & electrical system functionality

N/D	Accesa e provata per ispezione
N/D	Good
N/D	No
N/D	No
N/D	No
N/D	Good
N/D	Good
N/D	Good
N/D	No

Functionality drive and rotation

N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	Good

Inserire Misura (mm.) : 2000

Linkage Group

N/D	Good

Presenza di perdite? Se si, specificare da dove: : No

N/D	Good

Presenza di perdite? Se si, specificare da dove: : No

N/D	Good

Presenza di perdite? Se si, specificare da dove: : No

N/D	Good

Check 81/2008

Lights conditions:	Excellent - no needs repair
Condizioni specchietti:	Eccellente - non necessita riparazione
Stepladders & handrails conditions:	Good

Cameras conditions:	Broken or Chipped - needs repair
Flashing conditions:	Present and functioning
Controls been modified:	No
Presence of Exclusion Control Lever:	Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	Yes
Batteries box shielded:	Yes
Acustic alarm works properly:	Yes
Boardwalk presence:	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.