

SALES REPORT: VERMEER HG4000 - SN HXD1000124 - Year 2013

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: HG4000

Family: SHREDDER

Serial Number: HXD1000124

Order Number MU/MM: MU00734158

Construction year: 2013

Hour meter: 5367

General residual conditions Truck/Tyres: %

Machine main application:

Location: Stock Villa Autotrasp

Rating: ★★☆☆☆

Public price: 115.000 €

MACHINE CONFIGURATION

● Machine type Demolition ● ● nessun prevaglio ● undefined ● 19000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ●

ORIGINS & APPLICATION

◆ Machine Origins:

Purchase

MACHINE PHOTOS

◆ Il contaore e':

Funzionante







GENERAL APPEARANCE

◆ Painting Conditions Poor

FRANTOIO

◆ Spar conditions: Good

◆ Alimentatore: Buono

◆ Bocca del frantoio: Buono

◆ Usura mascelle: 70

◆ Usura corazze 70

◆ Scarico sotto frantoio: Buono

NASTRI

◆ Nastro principale (tappeto, raschiatori, rulli): Buono

◆ Nastro laterale scarto: NA - Non Applicabile

◆ Deferrizzatore: NA - Non Applicabile

◆ Sistema abbattimento polveri: NA - Non Applicabile

CARRO

◆ Condizioni generali carro Scarso

Functionality

◆ In quale stato è stata visionata la macchina:

Accesa e provata per ispezione

Engine & electrical system functionality

◆ Engine working conditions: Good

◆ Engine with oil leaks: No

◆ Engine presents blowby: Yes

◆ Engine present smokiness: No

◆ Radiator conditions: Very good

◆ Starter motor conditions: Very good

◆ Batteries/Cables conditions: Good

◆ Presence of electrical fault: Presente

If present, add details : Sostituzione centralina preventivo Vermeer € 2.000,00

Functionality drive and rotation

◆ Hydraulic pump conditions: Good

◆ Engine travel conditions: Good

Linkage Group

◆ Boom structure: Good

◆ Stick structure: Good

◆ Lights conditions:	Broken or Chipped - needs repair
◆ Condizioni specchietti:	Mancanti
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Not functioning
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	No
◆ Boardwalk presence:	Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.