

SALES REPORT: CATERPILLAR CB334EXW - SN C3D00101 - Year 2006

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: CB334EXW

Family: UTILITY COMPACTORS

Serial Number: C3D00101

Order Number MU/MM: MU00734779

Construction year: 2006

Hour meter: 4541

General residual conditions Truck/Tyres: %

Machine main application:

Location: Stock Padova

Rating: ★★☆☆☆

Public price: Ask


MACHINE CONFIGURATION

• Machine type Standard - GP • Quick Coupler System undefined • Steering type 4200 • Tyres type undefined • 4200 Kg • CE Mark • CE Certificate • Use and maintenance manual • Registration book & Licence plate Registration book & Licence plate GO AA457

MACHINE PHOTOS









GENERAL APPEARANCE

- ◆ Painting Conditions: Good

- ◆ Counterweight conditions: Good

- ◆ Frame/Bumper conditions: Good

- ◆ Door conditions: Good

- ◆ Central joint: Good

- ◆ Other notes: Raschia rulli da sostituire

Functionality

Engine & electrical system functionality

- ◆ In quale stato è stata visionata la macchina: Spenta e ferma

- ◆ Engine working conditions: Good

- ◆ Engine with oil leaks: Yes
If Yes, where : Rullo anteriore

- ◆ Engine presents blowby: No

- ◆ Engine present smokiness: No

- ◆ Radiator conditions: Good

- ◆ Batteries/Cables conditions: Excellent

- ◆ Presence of electrical fault: No

Functionality drive and rotation

- ◆ Hydraulic pump conditions: Good

◆ Engine travel conditions: Good

◆ Final drives conditions: Good

◆ Gear switches go/back conditions: Good

Linkage Group

◆ Hydraulic conditions linkage group: Buono

◆ Flexible pipes conditions: Good

◆ Annotazioni su: Rullo posteriore piegato verso destra , tamponi rotti , vibrazione posteriore da verificare .

Cabin and Tools

◆ Conditions internal cabin: Good

◆ Lights & Windshield present issues: Presents and functioning

Check 81/2008

◆ Condizioni freni: Buono

◆ Condizioni freno di Stazionamento: Buono

◆ Lights conditions: Excellent - no needs repair

◆ Condizioni specchietti: Rotto o Scheggiato - necessita riparazione

◆ Stepladders & handrails conditions: Good

◆ Flashing conditions: Not functioning

◆ Safety belt conditions: Present and valid



◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.