

SALES REPORT: KOMATSU PC35#KKOMA - SN 16610 - Year 2010

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: PC35#KKOMA

Family: MINI EXCAVATOR

Serial Number: 16610

Order Number MU/MM: MU00744941

Construction year: 2010

Hour meter: 3870

General residual conditions Truck/Tyres: 60 %

Machine main application: Basic application

Location: Stock Off.Buniotto

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Mono boom ● Plant features Hammer line ● Quick coupler Mechanic clack ● Bucket Standard 2 benne : pulizia canali + scavo da 50 cm Get Teeth 2 benne : pulizia canali + scavo da 50 cm ● Truck type Fixed ● Blade ● General Truck Residual 60% ● Cabin type Fixed standard ● Air Conditioning system ● 37 Kg ● CE Mark ● CE Certificate ● EPA Tag ● Use and maintenance manual

MACHINE PHOTOS

◆ Il contaore è:

Funzionante

◆ Annotazioni sul:

cingolo sinistro si blocca nella rotazione, riparato in CGT mesi fa con programma ape, si ripresenta ad intermittenza









◆ Painting Conditions Poor

◆ Counterweight conditions: Poor

◆ Frame/Bumper conditions: Poor

TRUCK

◆ Sprockets residual: 60

◆ Front idler wheel residual: 60

◆ Rollers upper/bottom residual: 60

◆ Chains residual: 50

Right side

◆ Door conditions (right): Good

◆ Spar conditions: Good

Left side

◆ Door conditions (left): Poor

◆ Door conditions (left): Good

◆ Spar conditions (left): Good

◆ Hood/Armor bottom conditions: Present and bash

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	Yes
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	Si

Functionality drive and rotation

◆ Hydraulic pump conditions:	Good
◆ Engine rotation conditions:	Good
◆ Engine travel conditions:	Good
◆ Final drives conditions:	Good
◆ Hydraulic joint conditions:	Good
	Presence of leaks : No
◆ Hydraulic joint conditions:	Good



Presence of leaks : No

Linkage Group

- ◆ Hydraulic conditions linkage group: No

- ◆ Boom structure: Good
Presence of welding/cracks : No

- ◆ Stick structure: Good
Presence of welding/cracks : No

- ◆ Flexible pipes conditions: Poor

- ◆ Boom cylinders conditions: Good
Leaks : Yes

- ◆ Stick cylinder conditions: Good
Leaks : Yes

- ◆ Bucket cylinder conditions: Good
Leaks : Yes

- ◆ Pins & Bushings boom conditions: Poor

- ◆ Pins & Bushings stick conditions: Poor

- ◆ Pins & Bushings bucket conditions: Poor

- ◆ Bucket & Get conditions: Good

- ◆ Quick Coupler conditions: Good

- ◆ Auto Lube working conditions: No

Cabin and Tools

- ◆ Conditions internal cabin: Good

- ◆ Flashing presents issues: No

- ◆ Lights & Windshield present issues: Not presents

- ◆ Air conditioning is working: Presente e non funzionante

- ◆ Back & side camera conditions: Not functioning

Check 81/2008

- ◆ Glass conditions: Broken or Chipped - needs repair

- ◆ Lights conditions: Broken or Chipped - needs repair

- ◆ Rear view mirrors conditions: Mancanti

- ◆ Stepladders & handrails conditions: Good

- ◆ Cameras conditions: Broken or Chipped - needs repair

- ◆ Flashing conditions: Not functioning

- ◆ Safety belt conditions: Present and valid

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes

- ◆ Are Tools Functional & Visible with tag: Yes

- ◆ Canopy completed and comes with keys and bolt: Yes

- ◆ All Pipes with no damage e/o scratches: No

- ◆ Batteries box shielded: Yes

- ◆ Acoustic alarm works properly: No



◆ Boardwalk presence:

Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.