

## SALES REPORT: HITACHI ZW220#KHITA - SN 00000282 - Year 2017

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** ZW220#KHITA

**Family:** MEDIUM WHEEL LOADER

**Serial Number:** 00000282

**Order Number MU/MM:** MU00745348

**Construction year:** 2017

**Hour meter:** 16551

**General residual conditions Truck/Tyres:** 80 %

**Machine main application:** Industry - corrosive field

**Location:** Stock ROMA

**Rating:** ★★☆☆☆

**Public price:** Ask

#### MACHINE CONFIGURATION

---

● Machine type HLA ● Steering type Command steering Presence of Command Steering No ● Differential Type Standard ● Transmission type Automatic ● Auxiliary Systems ● Bucket Ditch Cleaning Bucket 3,5mc Get Cover Blade ● Tyres type Standard ● General Tyres Residual 80 ● Rops Close ● Air Conditioning system ● Weight Scale ● Product Link ● 18500 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate undefined

MACHINE PHOTOS

---

◆ Il contaore e':

Funzionante



























## GENERAL APPEARANCE

---

- ◆ Painting Conditions: Good

---

- ◆ Counterweight conditions: Good

---

- Needs painting? : No

---

- ◆ Frame/Bumper conditions: Good

---

- ◆ Door conditions: Good

---

- ◆ Central joint: Good

---

- ◆ Fender/Mudguard conditions: Good

---

- ◆ Other notes: Leggere ammaccature su parafanghi e sulle scalette

---

## Tyres

---



◆ Front Tyres residual: 80

---

◆ Front Tyres residual: 80

---

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina: Spenta e ferma

---

◆ Engine working conditions: Poor

---

◆ Engine with oil leaks: No

---

◆ Engine presents blowby: No

---

◆ Oil-Water presence: No

---

◆ Engine present smokiness: No

---

◆ Radiator conditions: Good

---

◆ Starter motor conditions: Good

---

◆ Batteries/Cables conditions: Good

---

◆ Presence of electrical fault: Sì

If present, add details : Impianto adblue

---

◆ Annotazioni su: La pala va in protezione, scheda linea adblue da sostituire

---

### Functionality drive and rotation

---

◆ Hydraulic pump conditions: Good

---

◆ Engine travel conditions: NA - Not applicable



---

◆ Final drives conditions: Good

---

◆ Hydraulic joint conditions: Good

---

Presence of leaks : No

---

◆ Gear switches go/back conditions: Good

---

### Engine & electrical system functionality

---

◆ Engine working conditions: Good

---

◆ Radiator conditions: Good

---

◆ Starter motor conditions: Good

---

### Linkage Group

---

◆ Tenuta idraulica braccio (il braccio cala): No

---

◆ Boom structure: Good

---

Presence of welding/cracks : No

---

◆ Flexible pipes conditions: Good

---

◆ Lifting cylinders conditions: Good

---

◆ Bucket cylinder conditions: Good

---

◆ Pins & Bushings bucket conditions: Good

---

◆ Bucket & Get conditions: Good

---

◆ Quick Coupler conditions: NA - Not applicable

---

◆ Funzionamento Impianto Ingrassaggio Automatico: No

---



## Cabin and Tools

---

◆ Conditions internal cabin:	Good
◆ Lights & Windshield present issues:	Present and not functioning
◆ Air conditioning & Filters conditions:	Presents and functioning
◆ Back & side camera conditions:	Not functioning

## Check 81/2008

---

◆ Condizioni freni:	Buono
◆ Condizioni freno di Stazionamento:	Buono
◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Broken or Chipped - needs repair
◆ Condizioni specchietti:	Eccellente - non necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Present and functioning
◆ Safety belt conditions:	Present and expired
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes





- 
- ◆ All Pipes with no damage e/o scratches: Yes

---

  - ◆ Batteries box shielded: Yes

---

  - ◆ Acoustic alarm works properly: Yes

---

  - ◆ Boardwalk presence: Present and functioning
-



## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components-with 70/80% of life residue. Machine in security conditions.