

## SALES REPORT: CATERPILLAR 302.7DCR - SN LJL05### - Year 2019

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 302.7DCR

**Family:** MINI EXCAVATOR

**Serial Number:** LJL05###

**Order Number MU/MM:** MU00746908

**Construction year:** 2019

**Hour meter:** 2407

**General residual conditions Truck/Tyres:** 70 %

**Machine main application:** Basic application

**Machine availability date :** 12/11/2024

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

#### MACHINE CONFIGURATION

---

● Machine type Standard ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Hammer line ● Quick coupler Mechanic ● Bucket Standard 1 Get Teeth 3 ● Truck type Fixed ● Blade ● General Truck Residual 70% ● Cabin type Fixed standard ● 2500 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS

◆ Il contaore è:

Funzionante









## GENERAL APPEARANCE

---

- ◆ Painting Conditions Good

---

- ◆ Counterweight conditions: Good

---

- ◆ Frame/Bumper conditions: Good

## TRUCK

---

- ◆ Sprockets residual: 70

---

- ◆ Front idler wheel residual: 70

---

- ◆ Rollers upper/bottom residual: 70

---

- ◆ Chains residual: 70

## Right side

---

- ◆ Door conditions (right): Good

◆ Spar conditions: Good

---

**Left side**

---

◆ Door conditions (left): NA - Not applicable

---

◆ Door conditions (left): NA - Not applicable

---

◆ Spar conditions (left): NA - Not applicable

---

◆ Hood/Armor bottom conditions: Present and intact

---

**Functionality**

---

**Engine & electrical system functionality**

---

◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

---

◆ Engine working conditions: Good

---

◆ Engine with oil leaks: No

---

◆ Engine presents blowby: No

---

◆ Oil-Water presence: No

---

◆ Engine present smokiness: No

---

◆ Radiator conditions: Good

---

◆ Starter motor conditions: Good

---

◆ Batteries/Cables conditions: Good

---

◆ Presence of electrical fault: No

---

## Functionality drive and rotation

---

◆ Hydraulic pump conditions:	Good
◆ Engine rotation conditions:	Good
◆ Engine travel conditions:	Good
◆ Final drives conditions:	Good
◆ Hydraulic joint conditions:	Good Presence of leaks : No
◆ Hydraulic joint conditions:	Good Presence of leaks : No

## Linkage Group

---

◆ Hydraulic conditions linkage group:	No
◆ Boom structure:	Good Presence of welding/cracks : No
◆ Stick structure:	Good Presence of welding/cracks : No
◆ Flexible pipes conditions:	Good
◆ Boom cylinders conditions:	Good Leaks : No
◆ Stick cylinder conditions:	Good Leaks : No
◆ Bucket cylinder conditions:	Good Leaks : No
◆ Pins & Bushings boom conditions:	Good

- ◆ Pins & Bushings stick conditions: Good

---

- ◆ Pins & Bushings bucket conditions: Good

---

- ◆ Bucket & Get conditions: Good

---

- ◆ Quick Coupler conditions: Good

---

- ◆ Auto Lube working conditions: No

---

### Cabin and Tools

---

- ◆ Conditions internal cabin: Good

---

- ◆ Flashing presents issues: No

---

- ◆ Lights & Windshield present issues: Presents and functioning

---

- ◆ Air conditioning is working: Non Presente

---

- ◆ Back & side camera conditions: Not functioning

---

### Check 81/2008

---

- ◆ Glass conditions: Excellent - no needs repair

---

- ◆ Lights conditions: Excellent - no needs repair

---

- ◆ Rear view mirrors conditions: Mancanti

---

- ◆ Stepladders & handrails conditions: Good

---

- ◆ Cameras conditions: Broken or Chipped - needs repair

---

- ◆ Flashing conditions: Not functioning

---





◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.