

SALES REPORT: CATERPILLAR 289D - SN TAW01171 - Year 2014

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 289D

Family: COMPACT TRACK LOADER

Serial Number: TAW01171

Order Number MU/MM: MU00746944

Construction year: 2014

Hour meter: 5699

General residual conditions Truck/Tyres: 60 %

Machine main application: Basic application

Location: Stock Off.Buniotto

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Wasting configuration ● Rops Close ● Bucket Standard Get Get ● Plant features ● Cabin fog Side/Door superiore ● General Truck Residual 60% ● Air Conditioning system ● Product Link ● Antitheft alarm ● CE Mark ● CE Certificate ● undefined AJM887

MACHINE PHOTOS

◆ Il contaore e':

Funzionante







GENERAL APPEARANCE

◆ Painting Conditions	Poor
◆ Counterweight conditions	Poor
	Needs painting? : No
◆ Frame/Bumper conditions	Poor
◆ Door conditions (left)	Poor

Truck

◆ Front Idler residual	40
◆ Front drive sprocket residual:	40
◆ Bottom rollers residual:	40
◆ Grousers residual:	80
◆ Chains residual:	80

Functionality

Engine & electrical system functionality

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

- ◆ Engine working conditions: Poor

- ◆ Engine with oil leaks: No

- ◆ Engine presents blowby: Yes

- ◆ Oil-Water presence: Yes

- ◆ Engine present smokiness: Yes, blue

- ◆ Radiator conditions: Poor

- ◆ Starter motor conditions: Poor

- ◆ Batteries/Cables conditions: Poor

- ◆ Presence of electrical fault: Si

Functionality drive and rotation

- ◆ Hydraulic pump conditions: Poor

- ◆ Brakes and steering cluthces conditions: Poor

- ◆ Engine travel conditions: Poor

- ◆ Final drives conditions: Poor

Linkage Group

◆ Tenuta idraulica braccio (il braccio cala): No

◆ Boom structure: Poor

Photos

Presence of welding/cracks : No



◆ Flexible pipes conditions: Poor

◆ Pins & Bushings boom conditions: Poor

◆ Pins & Bushings stick conditions: Poor

◆ Pins & Bushings bucket conditions: Poor

◆ Bucket/Get conditions Poor

◆ Funzionamento Impianto Ingrassaggio Automatico: No

Cabin and Tools

◆ Conditions internal cabin: Good

◆ Lights & Windshield present issues_ Present and not functioning

◆ Air contidioning & Filters conditions: Present and not functioning

◆ Back & side camera conditions: Not functioning

Check 81/2008

◆ Glasses conditions: Excellent - no needs repair

◆ Lights conditions: Broken or Chipped - needs repair

◆ Condizioni specchietti: Eccellente - non necessita riparazione

◆ Stepladders & handrails conditions: NA - Not applicable

◆ Cameras conditions: Non presente

◆ Flashing conditions: Not functioning

◆ Safety belt conditions: Present and expired

◆ Controls been modified: No

◆ Presence of Exclusion Control Lever: Yes

◆ Are Tools Functional & Visible with tag: Yes

◆ Canopy completed and comes with keys and bolt: Yes

◆ All Pipes with no damage e/o scratches: No

◆ Batteries box shielded: Yes

◆ Acoustic alarm works properly: No

◆ Boardwalk presence: Not present

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components-with 70/80% of life residue. Machine in security conditions.