

SALES REPORT: CATERPILLAR AP600D - SN TFM00230 - Year 2010

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: AP600D

Family: ASPHALT PAVERS

Serial Number: TFM00230

Order Number MU/MM: MU00747501

Construction year: 2010

Hour meter: 4619

General residual conditions Truck/Tyres: %

Machine main application:

Location: Stock Torino

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard ● Boom type undefined ● Boom check valves ● Plant features ● Truck type ● Product Link girevoli ● EPA Tag ● 18000 Kg ● CE Mark ● CE Certificate ● ● Use and maintenance manual

MACHINE PHOTOS





GENERAL APPEARANCE

◆ Painting Conditions	Good
◆ Spar conditions:	Good
◆ Residual % - Tyres/Track:	40
◆ Residual % - Cushion:	40
◆ Seat condition:	Very good
◆ Engine working conditions:	Very good
◆ Radiator conditions:	Very good
◆ Batteries/Cables conditions:	Good

Functionality

SCREED

◆ Hydraulic pump conditions:	5 mt
◆ Brakes and steering clutch conditions:	20
◆ Final drives conditions:	30
◆ Residuo % Nastri:	40
◆ Residuo % Fondi	20
◆ Apertura massima Allargamenti (se presenti):	no
◆ Annotazioni su:	Banco da revisionare, tamper non integri, piastre al 20% alcune resistenze difettose

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	No

Functionality drive and rotation

- ◆ Hydraulic pump conditions: Good

- ◆ Engine travel conditions: Good

- ◆ Final drives conditions: Good

Linkage Group

- ◆ Boom structure: Good

Presenza di perdite? Se si, specificare da dove: : no

- ◆ Stick structure: Good

Presenza di perdite? Se si, specificare da dove: : no

- ◆ Flexible pipes conditions: Good

Presenza di perdite? Se si, specificare da dove: : no

- ◆ Boom cylinders conditions: Good

Check 81/2008

- ◆ Condizioni freni: Buono

- ◆ Condizioni freno di Stazionamento: Buono

- ◆ Lights conditions: Excellent - no needs repair

- ◆ Condizioni specchietti: Eccellente - non necessita riparazione

- ◆ Stepladders & handrails conditions: Good

- ◆ Cameras conditions: Broken or Chipped - needs repair



- ◆ Flashing conditions: Not functioning

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes
If No, are control levers protected to accidental functionality? : Yes

- ◆ Are Tools Functional & Visible with tag: Yes

- ◆ Canopy completed and comes with keys and bolt: Yes

- ◆ All Pipes with no damage e/o scratches: Yes

- ◆ Batteries box shielded: Yes

- ◆ Acoustic alarm works properly: Yes

- ◆ Boardwalk presence: Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.