

## SALES REPORT: CATERPILLAR 303 E CR - SN SGE01### - Year 2021

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 303 E CR

**Family:** MINI EXCAVATOR

**Serial Number:** SGE01###

**Order Number MU/MM:** MU00747503

**Construction year:** 2021

**Hour meter:** 1532

**General residual conditions Truck/Tyres:** 80 %

**Machine main application:** Basic application

**Machine availability date :** 15/11/2024

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

#### MACHINE CONFIGURATION

---

● Machine type Standard ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Hammer line ● Quick coupler Mechanic 1200/700/300 ● Bucket Standard 3 Get Teeth 3 ● Truck type Hydraulic extendible ● Blade ● General Truck Residual 80% ● Cabin type Fixed standard ● Product Link ● 3200 Kg ● CE Mark ● CE Certificate ● EPA Tag ● Use and maintenance manual

MACHINE PHOTOS

---

◆ Il contaore è:

Funzionante













**GENERAL APPEARANCE**

◆ Painting Conditions	Good
◆ Counterweight conditions:	Good
◆ Frame/Bumper conditions:	Good

**TRUCK**

◆ Sprockets residual:	80
◆ Front idler wheel residual:	80
◆ Rollers upper/bottom residual:	80
◆ Chains residual:	90

### Right side

◆ Door conditions (right):	Good
◆ Spar conditions:	Good

### Left side

◆ Door conditions (left):	NA - Not applicable
◆ Door conditions (left):	Good
◆ Spar conditions (left):	Good
◆ Hood/Armor bottom conditions:	Present and intact

## Functionality

### Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No



- 
- ◆ Oil-Water presence: No

---

  - ◆ Engine present smokiness: No

---

  - ◆ Radiator conditions: Good

---

  - ◆ Starter motor conditions: Good

---

  - ◆ Batteries/Cables conditions: Good

---

  - ◆ Presence of electrical fault: No
- 

**Functionality drive and rotation**

---

- ◆ Hydraulic pump conditions: Good

---

  - ◆ Engine rotation conditions: Good

---

  - ◆ Engine travel conditions: Good

---

  - ◆ Final drives conditions: Good

---

  - ◆ Hydraulic joint conditions: Good  
Presence of leaks : No

---

  - ◆ Hydraulic joint conditions: Good  
Presence of leaks : No
- 

**Linkage Group**

---

- ◆ Hydraulic conditions linkage group: No

---

- ◆ Boom structure: Good  
Presence of welding/cracks : No

---

- ◆ Stick structure: Good  
Presence of welding/cracks : No



---

◆ Flexible pipes conditions:	Good
◆ Boom cylinders conditions:	Good
	Leaks : No
◆ Stick cylinder conditions:	Good
	Leaks : No
◆ Bucket cylinder conditions:	Good
	Leaks : No
◆ Pins & Bushings boom conditions:	Good
◆ Pins & Bushings stick conditions:	Very good
◆ Pins & Bushings bucket conditions:	Good
◆ Bucket & Get conditions:	Good
◆ Quick Coupler conditions:	Good
◆ Auto Lube working conditions:	No

---

### Cabin and Tools

---

◆ Conditions internal cabin:	Good
◆ Flashing presents issues:	No
◆ Lights & Windshield present issues:	Presents and functioning
◆ Air conditioning is working:	Non Presente
◆ Back & side camera conditions:	Not functioning

---





◆ Glass conditions:	Excellent - no needs repair
◆ Lights conditions:	Excellent - no needs repair
◆ Rear view mirrors conditions:	Mancanti
◆ Stepladders & handrails conditions:	NA - Not applicable
◆ Cameras conditions:	Broken or Chipped - needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and valid
◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	Yes
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and functioning

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.