

SALES REPORT: DOPPSTADT DW2560 - SN W09256219A2D38113 - Year 2010

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: DW2560

Family: SHREDDER

Serial Number: W09256219A2D38113

Order Number MU/MM: MU00750861

Construction year: 2010

Hour meter: 4000

General residual conditions Truck/Tyres: %

Machine main application:

Location: Stock Villa Autotrasp

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

• Machine type Demolition • undefined • undefined • undefined • 19500 Kg • CE Mark • CE Certificate • Use and maintenance manual

ORIGINS & APPLICATION

◆ Machine Origins:

Different Purchase

MACHINE PHOTOS

◆ Il contaore e':

Rotto





GENERAL APPEARANCE

◆ Painting Conditions Poor

FRANTOIO

◆ Spar conditions: Good

◆ Alimentatore: Buono

◆ Bocca del frantoio: Buono

◆ Usura mascelle: 30

◆ Usura corazze 30

◆ Scarico sotto frantoio: Scarso

NASTRI

◆ Nastro principale (tappeto, raschiatori, rulli):	Scarso
◆ Nastro laterale scarto:	NA - Non Applicabile
◆ Deferrizzatore:	NA - Non Applicabile
◆ Sistema abbattimento polveri:	NA - Non Applicabile

CARRO

◆ Condizioni generali carro	Scarso
-----------------------------	--------

Functionality

◆ In quale stato è stata visionata la macchina:	Spenta e ferma
---	----------------

Engine & electrical system functionality

◆ Engine working conditions:	Good
◆ Engine with oil leaks:	Yes
◆ Engine presents blowby:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Poor
◆ Starter motor conditions:	Poor
◆ Batteries/Cables conditions:	Poor



◆ Presence of electrical fault: Presente

Functionality drive and rotation

◆ Hydraulic pump conditions: Good

◆ Engine travel conditions: NA - Not applicable

Linkage Group

◆ Boom structure: Poor

◆ Stick structure: Poor

Check 81/2008

◆ Lights conditions: Broken or Chipped - needs repair

◆ Condizioni specchietti: Mancanti

◆ Stepladders & handrails conditions: NA - Not applicable

◆ Cameras conditions: Excellent - no needs repair

◆ Flashing conditions: Not functioning

◆ Controls been modified: No

◆ Presence of Exclusion Control Lever: Yes

◆ Are Tools Functional & Visible with tag: No

◆ Canopy completed and comes with keys and bolt: No

◆ All Pipes with no damage e/o scratches: No



◆ Batteries box shielded: Yes

◆ Acoustic alarm works properly: No

◆ Boardwalk presence: Not present

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.