

## SALES REPORT: CATERPILLAR 938M - SN P5K00538 - Year 2019

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 938M

**Family:** MEDIUM WHEEL LOADER

**Serial Number:** P5K00538

**Order Number MU/MM:** MU00752883

**Construction year:** 2019

**Hour meter:** 9014

**General residual conditions Truck/Tyres:** 10 %

**Machine main application:** Industry - not corrosive field

**Location:** Stock Arezzo

**Rating:** ★★☆☆☆

**Public price:** Ask

#### MACHINE CONFIGURATION

---

● Machine type Standard - GP ● Steering type Command steering Presence of Command Steering No ● Differential Type Controlled Slippage ● Transmission type Hydrostatic ● Ride Control ● Auxiliary Systems ● Quick Coupler System ● Bucket Ditch Cleaning Bucket 5MC Get Cover Blade ● Tyres type Filled roccia ● General Tyres Residual 10 20.5 R25 ● Rops Close ● Air Conditioning system ● Auto Lube system ● Product Link ● 180000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate undefined

MACHINE PHOTOS

◆ Il contaore e':

Funzionante





**GENERAL APPEARANCE**

---

- ◆ Painting Conditions: Good

---

- ◆ Counterweight conditions: Good

---

- Needs painting? : No

---

- ◆ Frame/Bumper conditions: Good

---

- ◆ Door conditions: Good

---

- ◆ Central joint: Good

---

- ◆ Fender/Mudguard conditions: Good

---

**Tyres**

---

- ◆ Front Tyres residual: 10

---

◆ Front Tyres residual: 10

---

## Functionality

---

### Engine & electrical system functionality

---

◆ In quale stato è stata visionata la macchina: Spenta e ferma

---

◆ Engine working conditions: NA - Not applicable

---

◆ Engine with oil leaks: No

---

◆ Engine presents blowby: No

---

◆ Oil-Water presence: No

---

◆ Engine present smokiness: No

---

◆ Radiator conditions: Good

---

◆ Starter motor conditions: Good

---

◆ Batteries/Cables conditions: Good

---

◆ Presence of electrical fault: No

---

### Functionality drive and rotation

---

◆ Hydraulic pump conditions: Good

---

◆ Engine travel conditions: Good

---

◆ Final drives conditions: Good

---

◆ Hydraulic joint conditions: Good

Presence of leaks : No

◆ Gear switches go/back conditions: Good

### Engine & electrical system functionality

---

◆ Engine working conditions: Good

◆ Radiator conditions: Good

◆ Starter motor conditions: Good

### Linkage Group

---

◆ Tenuta idraulica braccio (il braccio cala): No

◆ Boom structure: Good

Presence of welding/cracks : No

◆ Flexible pipes conditions: Good

◆ Lifting cylinders conditions: Good

◆ Bucket cylinder conditions: Good

◆ Pins & Bushings bucket conditions: Good

◆ Bucket & Get conditions: Good

◆ Quick Coupler conditions: Good

◆ Funzionamento Impianto Ingrassaggio Automatico: Sì

### Cabin and Tools

---

◆ Conditions internal cabin: Good

- ◆ Lights & Windshield present issues: Presents and functioning

---

- ◆ Air conditioning & Filters conditions: Presents and functioning

---

- ◆ Back & side camera conditions: Present and functioning

---

### Check 81/2008

---

- ◆ Condizioni freni: Buono

---

- ◆ Condizioni freno di Stazionamento: Buono

---

- ◆ Glass conditions: Excellent - no needs repair

---

- ◆ Lights conditions: Excellent - no needs repair

---

- ◆ Condizioni specchietti: Eccellente - non necessita riparazione

---

- ◆ Stepladders & handrails conditions: Good

---

- ◆ Cameras conditions: Excellent - no needs repair

---

- ◆ Flashing conditions: Present and functioning

---

- ◆ Safety belt conditions: Present and valid

---

- ◆ Controls been modified: Yes

---

- ◆ Presence of Exclusion Control Lever: Yes

---

- If No, are control levers protected to accidental functionality? : Yes

---

- ◆ Are Tools Functional & Visible with tag: Yes

---

- ◆ Canopy completed and comes with keys and bolt: Yes

---

- ◆ All Pipes with no damage e/o scratches: Yes

---

- ◆ Batteries box shielded: Yes



---

◆ Acoustic alarm works properly: Yes

---

◆ Boardwalk presence: Not present

---

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.