

SALES REPORT: CATERPILLAR 301.8 - SN BFA01451 - Year 2002

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 301.8

Family: MINI EXCAVATOR

Serial Number: BFA01451

Order Number MU/MM: MU00753374

Construction year: 2002

Hour meter: 3214

General residual conditions Truck/Tyres: 30 %

Machine main application: Basic application

Location: Stock Off.Buniotto

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Mono boom ● Plant features Hammer line ● Bucket Standard Get Teeth ● Truck type Mechanic extendible ● Blade ● General Truck Residual 30% ● Cabin type Fixed standard ● 1900 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS


◆ Il contaore è:

Funzionante











GENERAL APPEARANCE

- ◆ Painting Conditions Poor

- ◆ Counterweight conditions: Poor

- ◆ Frame/Bumper conditions: Poor

TRUCK

- ◆ Sprockets residual: 30

- ◆ Front idler wheel residual: 30

- ◆ Rollers upper/bottom residual: 30

- ◆ Chains residual: 30

Right side

- ◆ Door conditions (right): Poor

- ◆ Spar conditions: Poor

Left side

- ◆ Door conditions (left): Poor

- ◆ Door conditions (left): Poor

- ◆ Spar conditions (left): Poor

- ◆ Hood/Armor bottom conditions: Not present



Functionality

Engine & electrical system functionality

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione

- ◆ Engine working conditions: Poor

- ◆ Engine with oil leaks: Yes

- ◆ Engine presents blowby: No

- ◆ Oil-Water presence: No

- ◆ Engine present smokiness: No

- ◆ Radiator conditions: Poor

- ◆ Starter motor conditions: Poor

- ◆ Batteries/Cables conditions: Poor

- ◆ Presence of electrical fault: Si

Functionality drive and rotation

- ◆ Hydraulic pump conditions: Poor

- ◆ Engine rotation conditions: Poor

- ◆ Engine travel conditions: Poor

- ◆ Final drives conditions: Poor

- ◆ Hydraulic joint conditions: Poor

Presence of leaks : Yes

◆ Hydraulic joint conditions: Poor
Presence of leaks : Yes

Linkage Group

◆ Hydraulic conditions linkage group: No

◆ Boom structure: Poor
Presence of welding/cracks : Yes

◆ Stick structure: Poor
Presence of welding/cracks : No

◆ Flexible pipes conditions: Poor

◆ Boom cylinders conditions: Poor
Leaks : Yes

◆ Stick cylinder conditions: Poor
Leaks : Yes

◆ Bucket cylinder conditions: Poor
Leaks : Yes

◆ Pins & Bushings boom conditions: Poor

◆ Pins & Bushings stick conditions: Poor

◆ Pins & Bushings bucket conditions: Poor

◆ Bucket & Get conditions: Poor

◆ Quick Coupler conditions: NA - Not applicable

◆ Auto Lube working conditions: No

Cabin and Tools

- ◆ Conditions internal cabin: Poor

- ◆ Flashing presents issues: No

- ◆ Lights & Windshield present issues: Not presents

- ◆ Air conditioning is working: Non Presente

- ◆ Back & side camera conditions: Not functioning

Check 81/2008

- ◆ Glass conditions: Broken or Chipped - needs repair

- ◆ Lights conditions: Broken or Chipped - needs repair

- ◆ Rear view mirrors conditions: Mancanti

- ◆ Stepladders & handrails conditions: Poor

- ◆ Cameras conditions: Broken or Chipped - needs repair

- ◆ Flashing conditions: Not functioning

- ◆ Safety belt conditions: Not present/Broken

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes

- If No, are control levers protected to accidental functionality? : Yes

- ◆ Are Tools Functional & Visible with tag: No

- ◆ Canopy completed and comes with keys and bolt: No

- ◆ All Pipes with no damage e/o scratches: No



◆ Batteries box shielded: Yes

◆ Acoustic alarm works properly: No

◆ Boardwalk presence: Not present

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.