

## SALES REPORT: CATERPILLAR BB-760 - SN B2B00102 - Year 2005

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** BB-760

**Family:** ASPHALT PAVERS

**Serial Number:** B2B00102

**Order Number MU/MM:** MU00758286

**Construction year:** 2005

**Hour meter:** 1961

**General residual conditions Truck/Tyres:** %

**Machine main application:**

**Machine availability date :** 17/03/2025

**Rating:** ★★☆☆☆

**Public price:** Ask

#### MACHINE CONFIGURATION

---

● Machine type Mass Excavator ● Boom type ● Boom check valves ● Truck type undefined ● Product Link undefined non girevoli ● EPA Tag undefined ● 18200 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS









## GENERAL APPEARANCE

◆ Painting Conditions	Very Good
◆ Spar conditions:	Very good
◆ Residual % - Tyres/Track:	80
◆ Residual % - Cushion:	80
◆ Seat condition:	Very good
◆ Engine working conditions:	Very good
◆ Radiator conditions:	Very good
◆ Batteries/Cables conditions:	Very good

## Functionality

### SCREED

◆ Hydraulic pump conditions:	non rilevata
◆ Brakes and steering clutch conditions:	70

◆ Engine travel conditions:	70
◆ Final drives conditions:	70
◆ Residuo % Nastri:	70
◆ Residuo % Fondi	70
◆ Apertura massima Allargamenti (se presenti):	non presenti

### Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
◆ Engine working conditions:	Very good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Very good
◆ Starter motor conditions:	Very good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	No

### Functionality drive and rotation

◆ Hydraulic pump conditions:	Good
◆ Engine travel conditions:	Good
◆ Final drives conditions:	Good

## Linkage Group

---

- ◆ Boom structure:
Good

---

- Presenza di perdite? Se si, specificare da dove: : nessuna perdita

---

- ◆ Stick structure:
Good

---

- Presenza di perdite? Se si, specificare da dove: : nessuna perdita

---

- ◆ Flexible pipes conditions:
Good

---

- Presenza di perdite? Se si, specificare da dove: : nessuna perdita

---

- ◆ Boom cylinders conditions:
Good

---

## Check 81/2008

---

- ◆ Condizioni freni:
Buono

---

- ◆ Condizioni freno di Stazionamento:
Buono

---

- ◆ Lights conditions:
Excellent - no needs repair

---

- ◆ Condizioni specchietti:
Rotto o Scheggiato - necessita riparazione

---

- ◆ Stepladders & handrails conditions:
Good

---

- ◆ Cameras conditions:
Broken or Chipped - needs repair

---

- ◆ Flashing conditions:
Not functioning

---

- ◆ Controls been modified:
No

---

- ◆ Presence of Exclusion Control Lever:
Yes

---

- ◆ Are Tools Functional & Visible with tag:
Yes

---

- ◆ Canopy completed and comes with keys and bolt:
Yes

---





- 
- ◆ All Pipes with no damage e/o scratches: Yes

---

  - ◆ Batteries box shielded: Yes

---

  - ◆ Acoustic alarm works properly: Yes

---

  - ◆ Boardwalk presence: Present and functioning
-

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.