SALES REPORT: CATERPILLAR 330 NG - SN PFN00299 - Year 2019

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 330 NG

Family: MEDIUM EXCAVATOR

Serial Number: PFN00299

Order Number MU/MM: MU00758387

Construction year: 2019

Hour meter: 9363

General residual conditions Truck/Tyres: 50 %

Machine main application: Basic application

Location: Stock Livorno

Rating: ★★★☆☆

Public price: 165.000 €

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Versatility impianto dedicato all'attacco rapido linea drenaggio ● Quick coupler Hydraulic CAT CW45S ● Bucket Standard ● Truck type Fixed ● General Truck Residual 50% ● Cabin type Fixed standard ● Cabin fog Upper ● Air Conditioning system ● Auto Lube system ● Product Link ● Antitheft alarm ● 30800 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual● AVAILABLE FROM JUNE

MACHINE PHOTOS

- Il contaore è: Funzionante

- Annotazioni sul: Escavatore dotato di sistema 3D originale completo, pedale traslazione rettilinea, pedale elettrico martello.

















GENERAL APPEARANCE

Painting Conditions	Very Good
Counterweight conditions:	Very good
Frame/Bumper conditions:	Very Good

TRUCK

Sprockets residual:	50
Front idler wheel residual:	50
Rollers upper/bottom residual:	50
Chains residual:	50

Right side

Door conditions (right):	Very good
Spar conditions:	Very good

Left side

Door conditions (left):	Very good
Door conditions (left):	Very good
Spar conditions (left):	Very good
Hood/Armor bottom conditions:	Present and intact

Functionality

Engine & electrical system functionality

In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
Engine working conditions:	Very good
Engine with oil leaks:	No
Engine presents blowby:	No
Oil-Water presence:	No
Engine present smokiness:	No
Radiator conditions:	Very good
Starter motor conditions:	Very good
Batteries/Cables conditions:	Very good
Presence of electrical fault:	No
Annotazioni su	MOTORE REVISIONATO A 7.000 ORE , VALVOLA EGR APPENA SOSTITUITA

Functionality drive and rotation

Hydraulic pump conditions:	Excellent
Engine rotation conditions:	Very good
Engine travel conditions:	Very good
Final drives conditions:	Very good
Hydraulic joint conditions:	Very good
	Presence of leaks : No

Hydraulic joint conditions:	Very good
	Presence of leaks : No
Annotazioni su:	POMPA IDRAULICA APPENA REVISIONATA

Linkage Group

Hydraulic conditions linkage group:	No
Boom structure:	Very good
	Presence of welding/cracks : No
Stick structure:	Very good
	Presence of welding/cracks : No
Flexible pipes conditions:	Very good
Boom cylinders conditions:	Very good
	Leaks : No
Stick cylinder conditions:	Very good
	Leaks : No
Bucket cylinder conditions:	Very good
	Leaks : No
Pins & Bushings boom conditions:	Very good
Pins & Bushings stick conditions:	Very good
Pins & Bushings bucket conditions:	Very good
Bucket & Get conditions:	Very good
Quick Coupler conditions:	Very good
Auto Lube working conditions:	SI

Cabin and Tools

Conditions internal cabin:	Very good
Flashing presents issues:	Yes
Lights & Windshield present issues:	Presents and functioning
Air conditioning is working:	Presente e funzionante
Back & side camera conditions:	Present and functioning

Check 81/2008

Glass conditions:	Excellent - no needs repair
Lights conditions:	Excellent - no needs repair
Rear view mirrors conditions:	Excellent - no needs repair
Stepladders & handrails conditions:	Very good
Cameras conditions:	Excellent - no needs repair
Flashing conditions:	Present and functioning
Safety belt conditions:	Present and valid
Controls been modified:	No
Presence of Exclusion Control Lever:	Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	Yes

Batteries box shielded:	Yes
Acustic alarm works properly:	Yes
Boardwalk presence:	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.