

SALES REPORT: HITACHI ZX240-5 - SN YL00801### - Year 2018

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: ZX240-5

Family: MEDIUM EXCAVATOR

Serial Number: YL00801###

Order Number MU/MM: MU00758826

Construction year: 2018

Hour meter: 3669

General residual conditions Truck/Tyres: 70 %

Machine main application: Basic application

Machine availability date : 18/02/2025

Location: Coming in

Rating: ★★☆☆☆

Public price: 95.000 €

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Versatility ● Bucket Standard 1,5 1700 mm Get Teeth portadenti e denti da sostituire - scarsaseconda benna mm 900 buona ● Truck type Fixed ● General Truck Residual 70% ● Cabin type Fixed standard ● Air Conditioning system ● Auto Lube system ● 240000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS











GENERAL APPEARANCE

| | |
|-----------------------------|------|
| ◆ Painting Conditions | Good |
| ◆ Counterweight conditions: | Good |
| ◆ Frame/Bumper conditions: | Good |

TRUCK

| | |
|----------------------------------|----|
| ◆ Sprockets residual: | 60 |
| ◆ Front idler wheel residual: | 60 |
| ◆ Rollers upper/bottom residual: | 65 |
| ◆ Chains residual: | 70 |

Right side

- ◆ Door conditions (right): NA - Not applicable
 - ◆ Spar conditions: Good
-

Left side

- ◆ Door conditions (left): Good
 - ◆ Door conditions (left): Good
 - ◆ Spar conditions (left): Good
 - ◆ Hood/Armor bottom conditions: Present and intact
-

Functionality

Engine & electrical system functionality

- ◆ In quale stato è stata visionata la macchina: Accesa e provata per ispezione
- ◆ Engine working conditions: Very good
- ◆ Engine with oil leaks: No
- ◆ Engine presents blowby: No
- ◆ Oil-Water presence: No
- ◆ Engine present smokiness: No
- ◆ Radiator conditions: Good
- ◆ Starter motor conditions: Good



◆ Batteries/Cables conditions: Good

◆ Presence of electrical fault: No

Functionality drive and rotation

◆ Hydraulic pump conditions: Very good

◆ Engine rotation conditions: Good

◆ Engine travel conditions: Good

◆ Final drives conditions: Good

◆ Hydraulic joint conditions: Good

Presence of leaks : No

◆ Hydraulic joint conditions: Good

Presence of leaks : No

Linkage Group

◆ Hydraulic conditions linkage group: No

◆ Boom structure: Good

Presence of welding/cracks : No

◆ Stick structure: Good

Presence of welding/cracks : No

◆ Flexible pipes conditions: Good

◆ Boom cylinders conditions: Good

Leaks : No

◆ Stick cylinder conditions: Good

Leaks : No



| | |
|--------------------------------------|---------------------|
| ◆ Bucket cylinder conditions: | Good |
| | Leaks : No |
| ◆ Pins & Bushings boom conditions: | Good |
| ◆ Pins & Bushings stick conditions: | Good |
| ◆ Pins & Bushings bucket conditions: | Good |
| ◆ Bucket & Get conditions: | Good |
| ◆ Quick Coupler conditions: | NA - Not applicable |
| ◆ Auto Lube working conditions: | SI |

Cabin and Tools

| | |
|---------------------------------------|---------------------------------|
| ◆ Conditions internal cabin: | Very good |
| ◆ Flashing presents issues: | No |
| ◆ Lights & Windshield present issues: | Presents and functioning |
| ◆ Air conditioning is working: | Presente e funzionante |
| ◆ Back & side camera conditions: | Present and functioning |
| ◆ Annotazioni su: | 1 post + 2 laterali funzionanti |

Check 81/2008

| | |
|---------------------------------|----------------------------------|
| ◆ Glass conditions: | Excellent - no needs repair |
| ◆ Lights conditions: | Excellent - no needs repair |
| ◆ Rear view mirrors conditions: | Broken or Chipped - needs repair |



| | |
|--|-----------------------------|
| ◆ Stepladders & handrails conditions: | Good |
| ◆ Cameras conditions: | Excellent - no needs repair |
| ◆ Flashing conditions: | Not functioning |
| ◆ Safety belt conditions: | Present and expired |
| ◆ Controls been modified: | No |
| ◆ Presence of Exclusion Control Lever: | Yes |
| ◆ Are Tools Functional & Visible with tag: | Yes |
| ◆ Canopy completed and comes with keys and bolt: | Yes |
| ◆ All Pipes with no damage e/o scratches: | Yes |
| ◆ Batteries box shielded: | Yes |
| ◆ Acoustic alarm works properly: | Yes |
| ◆ Boardwalk presence: | Present and functioning |

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.