

SALES REPORT: CATERPILLAR 246C ZDC - SN JAY05877 - Year 2011

This Report is a summary about observations comes out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 246C ZDC

Family: SKID STEER LOADER

Serial Number: JAY05877

Order Number MU/MM: MU00760769

Construction year: 2011

Hour meter: 6417

General residual conditions Truck/Tyres: 30 %

Machine main application: Basic application

Location: Stock Off.Buniotto

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

• Machine type Wasting configuration • Rops Close • Bucket Standard • Plant features • • General Truck Residual 30% • Air Conditioning system • Product Link • 3438 Kg • CE Mark • CE Certificate • Use and maintenance manual • undefined AHR338

MACHINE PHOTOS

◆ Il contaore e':

Funzionante







GENERAL APPEARANCE

◆ Painting Conditions	Poor
◆ Counterweight conditions	Good
	Needs painting? : No
◆ Frame/Bumper conditions	Good
◆ Door conditions (left)	NA - Not applicable
◆ Other notes	porta anteriore rotta

Truck

◆ Front Idler residual	30
◆ Front drive sprocket residual:	70

Functionality

Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
<hr/>	
◆ Engine working conditions:	Poor
<hr/>	
◆ Engine with oil leaks:	No
<hr/>	
◆ Engine presents blowby:	No
<hr/>	
◆ Oil-Water presence:	No
<hr/>	
◆ Engine present smokiness:	No
<hr/>	
◆ Radiator conditions:	Good
<hr/>	
◆ Starter motor conditions:	Good
<hr/>	
◆ Batteries/Cables conditions:	Good
<hr/>	
◆ Presence of electrical fault:	Si
<hr/>	

Functionality drive and rotation

◆ Hydraulic pump conditions:	Poor
<hr/>	
◆ Brakes and steering cluthces conditions:	Good
<hr/>	
◆ Engine travel conditions:	Good
<hr/>	
◆ Final drives conditions:	Good
<hr/>	
◆ Annotazioni su:	BULBO PRESSIONE IDRAULICO DA SOSTITUIRE
<hr/>	

Linkage Group

◆ Tenuta idraulica braccio (il braccio cala): No

◆ Boom structure: Good

Photos

Presence of welding/cracks : No



◆ Flexible pipes conditions: Good

◆ Pins & Bushings boom conditions: Good

◆ Pins & Bushings stick conditions: Good

◆ Pins & Bushings bucket conditions: Poor

◆ Bucket/Get conditions Good

◆ Funzionamento Impianto Ingrassaggio Automatico: No

Cabin and Tools

- ◆ Conditions internal cabin: Poor
 Other notes : SEDILE DANNEGGIATO, PORTIERA MANCANTE, PULSANTI JOYSTICK MNCANI

- ◆ Lights & Windshield present issues_ Not presents

- ◆ Air contidioning & Filters conditions: Present and not functioning

- ◆ Back & side camera conditions: Not functioning

Check 81/2008

- ◆ Glasses conditions: Broken or Chipped - needs repair

- ◆ Lights conditions: Broken or Chipped - needs repair

- ◆ Condizioni specchietti: Mancanti

- ◆ Stepladders & handrails conditions: Good

- ◆ Cameras conditions: Non presente

- ◆ Flashing conditions: Not functioning

- ◆ Safety belt conditions: Present and expired

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes

- ◆ Are Tools Functional & Visible with tag: Yes

- ◆ Canopy completed and comes with keys and bolt: Yes

- ◆ All Pipes with no damage e/o scratches: Yes



◆ Batteries box shielded: Yes

◆ Acoustic alarm works properly: No

◆ Boardwalk presence: Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.