

SALES REPORT: CATERPILLAR 730 - SN AGF01### - Year 2004

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 730

Family: ARTICULATED TRUCKS

Serial Number: AGF01###

Order Number MU/MM: MU00763554

Construction year: 2004

Hour meter: 16224

General residual conditions Truck/Tyres: 70 %

Machine main application: Basic application

Machine availability date : 18/04/2025

Location: Coming in

Rating: ★★☆☆☆

Public price: 100.000 €

MACHINE CONFIGURATION

● Machine type Standard - GP ● ● Differential Type Standard ● Transmission type Automatic ● Tyres type Standard ● General Tyres Residual 70 23,5R25 ECOMEGA ● Air Conditioning system ● 22000 Kg ● CE Mark ● CE Certificate ● Registration book & Licence plate undefined

MACHINE PHOTOS











GENERAL APPEARANCE

◆ Painting Conditions:	Poor
◆ Front axle conditions:	Good
◆ Rear axles conditions:	Good
◆ Frame/Bumper conditions:	Good

◆ Door conditions: Good

◆ Cab/Canopy conditions: Good

◆ Fender/Mudguard conditions: Good

TYRES

◆ 1st Axle Tyres residual: 70

◆ Residual percentage 60

◆ 3rd Axle Tyres residual: 70

Functionality

Engine & electrical system functionality

◆ MACHINE STATUS DURING CHECK Tuned on at work

◆ Engine working conditions: Good

◆ Engine with oil leaks: Yes

If Yes, where : PACKING STELO PISTONE IDR. DI SOLLEVAMENTO CASSONE

◆ Engine presents blowby: No

◆ Oil-Water presence: No

◆ Engine present smokiness: No

◆ Radiator conditions: Good

◆ Starter motor conditions: Good

◆ Batteries/Cables conditions: Good



◆ Presence of electrical fault: No

Functionality drive and rotation

◆ Hydraulic pump conditions: Good

◆ Engine travel conditions: Good

◆ Final drives conditions: Good

◆ Hydraulic joint conditions: Good

Presence of leaks : No

◆ Gear switches go/back conditions: Good

◆ Brakes conditions: Good

Cabin and Tools

◆ Conditions internal cabin: Good

◆ Lights & Windshield present issues: Present and not functioning

◆ Air conditioning & Filters conditions: Present and not functioning

◆ Back & side camera conditions: Not functioning

Check 81/2008

◆ Glass conditions: Broken or Chipped - needs repair

◆ Lights conditions: Broken or Chipped - needs repair

◆ Mirrors conditions: Excellent - no reparation needed



- ◆ Stepladders & handrails conditions: Good

- ◆ Cameras conditions: Broken or Chipped - needs repair

- ◆ Flashing conditions: Not functioning

- ◆ Safety belt conditions: Present and valid

- ◆ Controls been modified: No

- ◆ Presence of Exclusion Control Lever: Yes
If No, are control levers protected to accidental functionality? : Yes

- ◆ Are Tools Functional & Visible with tag: Yes

- ◆ Canopy completed and comes with keys and bolt: Yes

- ◆ All Pipes with no damage e/o scratches: Yes

- ◆ Batteries box shielded: Yes

- ◆ Acoustic alarm works properly: Yes

- ◆ Boardwalk presence: Present and functioning

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.