

SALES REPORT: CATERPILLAR 730 - SN 3T301245 - Year 2020

This Report is a summary about observations came out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 730

Family: ARTICULATED TRUCKS

Serial Number: 3T301245

Order Number MU/MM: MU00769202

Construction year: 2020

Hour meter: 5462

General residual conditions Truck/Tyres: 40 %

Machine main application: Basic application

Location: Stock Milano Usato

Rating: ★★☆☆☆

Public price: Ask

MACHINE CONFIGURATION

● Machine type Standard - GP ● Forks ● ● Bucket ● Differential Type Self-Locking ● Transmission type Automatic ● Ride Control ● Tyres type Standard ● General Tyres Residual 40 23.5/25 DUE STELLE MICHELIN ● Air Conditioning system ● Auto Lube system ● Product Link ● 24000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate undefined

MACHINE PHOTOS







GENERAL APPEARANCE

◆ Painting Conditions:	Very Good
◆ Front axle conditions:	Good
◆ Rear axles conditions:	Good
◆ Frame/Bumper conditions:	Very Good
◆ Door conditions:	Good
◆ Cab/Canopy conditions:	Good
◆ Fender/Mudguard conditions:	Good

TYRES

◆ 1st Axle Tyres residual:	50
----------------------------	----

◆ Residual percentage	60
◆ 3rd Axle Tyres residual:	40

Functionality

Engine & electrical system functionality

◆ MACHINE STATUS DURING CHECK	Turned on just for inspection
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No
◆ Radiator conditions:	Good
◆ Starter motor conditions:	Good
◆ Batteries/Cables conditions:	Good
◆ Presence of electrical fault:	No

Functionality drive and rotation

◆ Hydraulic pump conditions:	Good
◆ Engine travel conditions:	Good
◆ Final drives conditions:	Good

◆ Hydraulic joint conditions: Good
Presence of leaks : No

◆ Gear switches go/back conditions: Good

◆ Brakes conditions: Good

Cabin and Tools

◆ Conditions internal cabin: Good

◆ Lights & Windshield present issues: Presents and functioning

◆ Air conditioning & Filters conditions: Presents and functioning

◆ Back & side camera conditions: Present and functioning

Check 81/2008

◆ Glass conditions: Excellent - no needs repair

◆ Lights conditions: Excellent - no needs repair

◆ Mirrors conditions: Excellent - no reparation needed

◆ Stepladders & handrails conditions: Very good

◆ Cameras conditions: Excellent - no needs repair

◆ Flashing conditions: Present and functioning

◆ Safety belt conditions: Present and valid

◆ Controls been modified: No

◆ Presence of Exclusion Control Lever: Yes



-
- ◆ Are Tools Functional & Visible with tag: Yes

 - ◆ Canopy completed and comes with keys and bolt: Yes

 - ◆ All Pipes with no damage e/o scratches: Yes

 - ◆ Batteries box shielded: Yes

 - ◆ Acoustic alarm works properly: Yes

 - ◆ Boardwalk presence: Present and functioning
-

Valutazione Macchina

★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.

Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.

Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".

Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo.

Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ Good (G)

Machine is in good condition and operational, with no structural issues.

Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.

Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.

No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".

Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one.

Main components-with 70/80% of life residue. Machine in security conditions.