SALES REPORT: CATERPILLAR 315F - SN TDY10491 - Year 2017

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: 315F

Family: SMALL EXCAVATOR

Serial Number: TDY10491

Order Number MU/MM: MU00789844

Construction year: 2017

Hour meter: 6630

General residual conditions Truck/Tyres: 15 %

Machine main application: Basic application

Location: Stock Arezzo

Rating: ★★★☆☆

Public price: 70.000 €

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Triple boom ● Boom check valves ● Stick check valves ● Plant features Versatility ● Quick coupler Hydraulic ● Bucket Standard Get Teeth ● Truck type Fixed ● Blade ● General Truck Residual 50% ● Cabin type Fixed standard ● Air Conditioning system ● Product Link ● 160000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual

MACHINE PHOTOS

- Il contaore è: Funzionante






CAT
315F




CAT













GENERAL APPEARANCE

Painting Conditions	Good
Counterweight conditions:	Good
Frame/Bumper conditions:	Good

TRUCK

Sprockets residual:	50
Front idler wheel residual:	50
Rollers upper/bottom residual:	40
Chains residual:	40

Right side

Door conditions (right):	Good
Spar conditions:	Good

Left side

Door conditions (left):	Good
Door conditions (left):	Good
Spar conditions (left):	Good
Hood/Armor bottom conditions:	Present and intact

Functionality

Engine & electrical system functionality

In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
Engine working conditions:	Very good
Engine with oil leaks:	No
Engine presents blowby:	No
Oil-Water presence:	No
Engine present smokiness:	No
Radiator conditions:	Good
Starter motor conditions:	Good
Batteries/Cables conditions:	Good
Presence of electrical fault:	No

Functionality drive and rotation

Hydraulic pump conditions:	Good
Engine rotation conditions:	Good
Engine travel conditions:	Good
Final drives conditions:	Good
Hydraulic joint conditions:	Good Presence of leaks : No
Hydraulic joint conditions:	Good Presence of leaks : No

Linkage Group

Hydraulic conditions linkage group:	No
Boom structure:	Good
	Presence of welding/cracks : No
Stick structure:	Good
	Presence of welding/cracks : No
Flexible pipes conditions:	Good
Boom cylinders conditions:	Good
	Leaks : No
Stick cylinder conditions:	Good
	Leaks : No
Bucket cylinder conditions:	Good
	Leaks : No
Pins & Bushings boom conditions:	Good
Pins & Bushings stick conditions:	Good
Pins & Bushings bucket conditions:	Good
Bucket & Get conditions:	Poor
Quick Coupler conditions:	Good
Auto Lube working conditions:	No

Cabin and Tools

Conditions internal cabin:	Good

Flashing presents issues:	No
Lights & Windshield present issues:	Presents and functioning
Air conditioning is working:	Presente e funzionante
Back & side camera conditions:	Present and functioning

Check 81/2008

Glass conditions:	Excellent - no needs repair
Lights conditions:	Excellent - no needs repair
Rear view mirrors conditions:	Excellent - no needs repair
Stepladders & handrails conditions:	Good
Cameras conditions:	Excellent - no needs repair
Flashing conditions:	Present and functioning
Safety belt conditions:	Present and valid
Controls been modified:	No
Presence of Exclusion Control Lever:	Yes
	If No, are control levers protected to accidental funcionality? : Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes
All Pipes with no damage e/o scratches:	Yes
Batteries box shielded:	Yes
Acustic alarm works properly:	Yes

- Boardwalk presence: Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.