SALES REPORT: CATERPILLAR MH 3024 - SN FM400126 - Year 2015

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: MH 3024

Family: WHEEL EXCAVATOR

Serial Number: FM400126

Order Number MU/MM: MU00790913

Construction year: 2015

Hour meter: 12987

General residual conditions Truck/Tyres: 10 %

Machine main application: Industry - not corrosive field

Location: Stock CASERTA

Rating: ★★★☆☆

Public price: 55.000 €

MACHINE CONFIGURATION

● Machine type Material Handling MH ● Boom type Mono boom ● Boom check valves ● Stick check valves ● Plant features Versatility No polipo macchina senza polipo ● Tyres type Twin Wheel ● General Tyres Residual 10 10.00-20 Globe ● Blade ● Stabilizers four Stabilizers ● Cabin type Hydraulic lift ● Cabin fog Front superiore ● Air Conditioning system ● Auto lube system Operation Yes ● Product Link ● 25550 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate No Registration book & Licence plate

MACHINE PHOTOS









GENERAL APPEARANCE

Painting Conditions	Good
Counterweight conditions	Good
	Needs painting? : Yes
Frame / Bumper conditions	Good

Tyres

Front Tyres residual	10
Front Tyres residual	10

Right side

Door conditions (right)	Good
Spar conditions (right)	Good

Left side

Door conditions (left)	Good
Door conditions (left)	Good
Spar conditions (left)	Good
Hood / Armor bottom conditions	Present and intact

Functionality

Engine & electrical system functionality

In quale stato è stata visionata la macchina:	Accesa e funzionante "al lavoro"
Engine functionality conditions	Good
Engine with oil leaks	No
Engine presents blowby	No
Oil-Water presence	No
Engine present smokiness	No
Radiator conditions	Good
Starter motor conditions	Good
Batteries/Cables conditions	Good
Presence of electrical fault	No
	If present, add details : Da controllare

Functionality drive and rotation

Hydraulic pump conditions	Good
Engine rotation conditions	Good
Engine travel conditions	Good
Final drives conditions	Good
Hydraulic joint conditions	Good
	Presence of leaks : No
Hydraulic joint conditions	Good

Presence of leaks : No

- Tenuta idraulica braccio (il braccio cala): No

Linkage Group

- Hydraulic conditions linkage group (Boom is lowering?) Yes
- Boom structure Good

  Presence of welding/cracks : No
- Stick structure Good

  Presence of welding/cracks : No
- Flexible pipes conditions Good
- Boom cylinders conditions Good

  Leaks : No
- Stick cylinder conditions Good

  Leaks : No
- Bucket / Grapple cylinder conditions Good

  Leaks : No
- Pins & Bushings boom conditions Good
- Pins & Bushings stick conditions Good
- Pins & Bushings bucket conditions Good
- Bucket / Grapple & Get conditions NA - Not applicable
- Quick Coupler conditions NA - Not applicable
- Funzionamento Impianto Ingrassaggio Automatico: Sì

Cabin and Tools

Conditions internal cabin	Good
Flashing presents issues	No
Lights & Windshield present issues	Presents and functioning
Air contidioning & Filters conditions	Presents and functioning
Back & side camera conditions	Present and functioning

Check 81/2008

Condizioni freni:	Buono
Condizioni freno di Stazionamento:	Buono
Glass conditions	Broken or Chipped - needs repair
Lights conditions	Excellent - no needs repair
Rear view mirrors conditions	Broken or Chipped - needs repair
Stepladders & handrails conditions	Good
Cameras conditions	Excellent - no needs repair
Flashing conditions	Not functioning
Safety belt conditions	Present and expired
Controls been modified	Yes
Presence of Exclusion Control Lever	Yes
Are Tools Functional & Visible with tag	Yes
Canopy completed and comes with keys and bolt	Yes

All Pipes with no damage e/o scratches	Yes
Batteries box shielded	Yes
Acustic alarm works properly	Yes
Boardwalk presence	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.