SALES REPORT: CATERPILLAR D5H - SN 1DD01033 - Year 1990

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: D5H

Family: MEDIUM TRACK TYPE TRACTOR

Serial Number: 1DD01033

Order Number MU/MM: MU00794117

Construction year: 1990

Hour meter: 12072

General residual conditions Truck/Tyres: 50 %

Machine main application: Basic application

Location: Stock ROMA

Rating: ★★★☆☆

Public price: 19.500 €

MACHINE CONFIGURATION

● Machine type Standard GP ● Truck type XL ● Rops Close ● Steering Control Differential steering ● Blade ● Tow Bar ● General Truck Residual 50% ● 13000 Kg

MACHINE PHOTOS








CATERPILLAR


D5H LGP


D5H LGP


CATERPILLAR











GENERAL APPEARANCE

Painting Conditions:	Good
Main frame welds presence:	Presenti
Counterweight conditions:	Good
	Needs painting? : No

Frame/Bumper conditions:	Good
Cabin / Door / Lock conditions:	Good
Technical compartment doors conditions:	Good

Truck

Idler wheel residual:	50
Sprocket residual:	50
Upper roller residual:	50
Bottom roller residual:	50%
Grousers residual:	50
Chains residual:	50
Annotazioni su:	Carro largo 2750

Functionality

Engine & electrical system functionality

In which conditions the machine it's been tested:	Turned off & still
Engine working conditions:	Good
Engine with oil leaks:	No
Engine presents blowby:	No
Oil-Water presence:	No

- Engine present smokiness: No
- Radiator conditions: Good
- Starter motor conditions: Good
- Batteries/Cables conditions: Good
- Presence of electrical fault: Presenti

Functionality drive and rotation

- Hydraulic pump conditions: Good
- Brakes and steering clutch conditions: Good
- Engine travel conditions: Poor
- Final drives conditions: Good
- Annotazioni su: La trasmissione scalda, dopo un po si ferma

Thrust group

- Lifting cylinders conditions: Poor
- Angle cylinders conditions: Poor

  Presence of welding/cracks : No
- TILT conditions: Good
- Ripper cylinder conditions: NA - Not applicable
- Flexible pipes conditions Good
- Blade pins conditions: Good
- Bucket conditions: Good

Auto Lube system is working:	Si

Cabin and Tools

Conditions internal cabin:	Good
	Other notes : Sedile da rifoderare
Lights & Windshield present issues:	Presents and functioning
Air contidioning & Filters conditions:	Not functioning
Back & side camera conditions:	Not functioning

Check 81/2008

Glass conditions:	Excellent - no needs repair
Lights conditions:	Broken or Chipped - needs repair
Condizioni specchietti:	Mancanti
Stepladders & handrails conditions:	Good
Cameras conditions:	Broken or Chipped - needs repair
Flashing conditions:	Not functioning
Safety belt conditions:	Present and expired
Controls been modified:	No
Presence of Exclusion Control Lever:	Yes
Are Tools Functional & Visible with tag:	Yes
Canopy completed and comes with keys and bolt:	Yes

All Pipes with no damage e/o scratches:	Yes
Batteries box shielded:	Yes
Acustic alarm works properly:	Yes
Boardwalk presence:	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.