SALES REPORT: CATERPILLAR M315C - SN H2B00391 - Year 2006

This Report is a summary about observations cames out from technical inspection done by our specialised technician.

GENERAL CONDITIONS

MACHINE DATA

Model: M315C

Family: WHEEL EXCAVATOR

Serial Number: H2B00391

Order Number MU/MM: MU00795915

Construction year: 2006

Hour meter: 15550

General residual conditions Truck/Tyres: 5 %

Machine main application: Basic application

Location: Stock Deposito Dini

Rating: ★★★☆☆

Public price: 33.000 €

MACHINE CONFIGURATION

● Machine type Standard ● Boom type Triple boom ● Boom check valves ● Stick check valves ● Plant features Versatility ● Quick coupler Mechanic ● Bucket / Grapple Standard ● Tyres type Twin Wheel ● General Tyres Residual 50 00 00 ● Stabilizers 2 Stabilizers ● Cabin type Fixed standard ● Air Conditioning system Operation Yes ● 170000 Kg ● CE Mark ● CE Certificate ● Use and maintenance manual ● Registration book & Licence plate Registration book & Licence plate

MACHINE PHOTOS

- Il contaore e': Funzionante








CAT
40

















M 315C
CAT




CAT
CATERPILLAR
CAT
CATERPILLAR
CE
KW
91
2006
kg
10150
MADE IN
FRANCE


CAT


CAT










CAT
CATERPILLAR
CE
KW
91
2006
kg
10150







GENERAL APPEARANCE

Painting Conditions	Good
Counterweight conditions	Good
	Needs painting? : No
Frame / Bumper conditions	Good

Tyres

N/D	50
N/D	50

Right side

N/D	Good
N/D	Good

Left side

N/D	Good
N/D	Good
N/D	Good
Hood / Armor bottom conditions	Present and intact

Functionality

Engine & electrical system functionality

N/D	Accesa e funzionante "al lavoro"

N/D	Good
N/D	No
N/D	No
N/D	No
N/D	No
N/D	Good
N/D	Good
N/D	Good
N/D	No

Functionality drive and rotation

N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	Good Presence of leaks : No
N/D	Good Presence of leaks : No
N/D	No

Linkage Group

N/D	No
N/D	Good Presence of welding/cracks : No
N/D	Good Presence of welding/cracks : No
N/D	Good
N/D	Good Leaks : No
N/D	Good Leaks : No
N/D	Good Leaks : No
N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	Good
N/D	No

Cabin and Tools

Conditions internal cabin	Good
Flashing presents issues	Yes

Lights & Windshield present issues	Present and not functioning
Air contidioning & Filters conditions	Presents and functioning
Back & side camera conditions	Not functioning

Check 81/2008

Condizioni freni:	Buono
Condizioni freno di Stazionamento:	Buono
Glass conditions	Excellent - no needs repair
Lights conditions	Excellent - no needs repair
Rear view mirrors conditions	Broken or Chipped - needs repair
Stepladders & handrails conditions	Good
Cameras conditions	Broken or Chipped - needs repair
Flashing conditions	Present and functioning
Safety belt conditions	Present and expired
Controls been modified	No
Presence of Exclusion Control Lever	Yes
	If No, are control levers protected to accidental funcionality? : Yes
Are Tools Functional & Visible with tag	Yes
Canopy completed and comes with keys and bolt	Yes
All Pipes with no damage e/o scratches	Yes
Batteries box shielded	Yes

Acustic alarm works properly	No
Boardwalk presence	Present and functioning

Valutazione Macchina

★ **Non Funzionante (NF)**

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

★★ **Scarso (S)**

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

★★★ **Buono (B)**

La macchina si presenta in buone condizioni sia estetiche che di funzionamento.
Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

★★★★ **Molto Buono (O)**

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate.
Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova".
Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

★★★★★ **Eccellente (E)**

La macchina si presenta in condizioni eccellenti, prossime al nuovo.
Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

Machine Rating

★ **Not Working (NW)**

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

★★ **Poor (P)**

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

★★★ **Good (G)**

Machine is in good condition and operational, with no structural issues.
Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted.
Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

★★★★ **Very Good (VG)**

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours.
No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New".
Main components with 50/60% of life residue. Machine in security conditions.

★★★★★ **Excellent (E)**

Machine is in excellent condition, comparable to a new one.
Main components with 70/80% of life residue. Machine in security conditions.