

## SALES REPORT: CATERPILLAR 226D3 - SN D5R00### - Year 2019

This Report is a summary about observations came out from technical inspection done by our specialised technician.

### GENERAL CONDITIONS

---

#### MACHINE DATA

---

**Model:** 226D3

**Family:** MINI DOZER

**Serial Number:** D5R00###

**Order Number MU/MM:** MU00798354

**Construction year:** 2019

**Hour meter:** 2681

**General residual conditions Truck/Tyres:** 60 %

**Machine main application:** Basic application

**Machine availability date :** 17/11/2025

**Location:** Coming in

**Rating:** ★★☆☆☆

**Public price:** Ask

#### MACHINE CONFIGURATION

---


• Machine type Wasting configuration • Rops Open • Bucket Standard Get Cover Blade • Plant features • General Truck Residual 60% • Product Link • 2835 Kg • CE Mark • CE Certificate • Use and maintenance manual • undefined ALS 802

**MACHINE PHOTOS**

◆ Il contaore e':

Funzionante





◆ Painting Conditions	Good
◆ Counterweight conditions	Good
	Needs painting? : No
◆ Frame/Bumper conditions	Good
◆ Door conditions (left)	Poor

### Truck

◆ Front Idler residual	60
◆ Front drive sprocket residual:	60
◆ Bottom rollers residual:	60
◆ Grousers residual:	60
◆ Chains residual:	60

### Functionality

#### Engine & electrical system functionality

◆ In quale stato è stata visionata la macchina:	Accesa e provata per ispezione
◆ Engine working conditions:	Good
◆ Engine with oil leaks:	No
◆ Engine presents blowby:	No
◆ Oil-Water presence:	No
◆ Engine present smokiness:	No

- ◆ Radiator conditions: Good

---

- ◆ Starter motor conditions: Good

---

- ◆ Batteries/Cables conditions: Good

---

- ◆ Presence of electrical fault: Si

---

**Functionality drive and rotation**

---

- ◆ Hydraulic pump conditions: Good

---

- ◆ Brakes and steering cluthces conditions: Good

---

- ◆ Engine travel conditions: Good

---

- ◆ Final drives conditions: Good

---

**Linkage Group**

---

- ◆ Tenuta idraulica braccio (il braccio cala): No

---

- ◆ Boom structure: Good

Photos

Presence of welding/cracks : No



- ◆ Flexible pipes conditions: Poor

---

◆ Pins & Bushings boom conditions:	Good
◆ Pins & Bushings stick conditions:	Good
◆ Pins & Bushings bucket conditions:	Good
◆ Bucket/Get conditions	Good
◆ Funzionamento Impianto Ingrassaggio Automatico:	No

### Cabin and Tools

---

◆ Conditions internal cabin:	Good
◆ Lights & Windshield present issues_	Present and not functioning
◆ Air contidioning & Filters conditions:	Not functioning
◆ Back & side camera conditions:	Present and functioning

### Check 81/2008

---

◆ Glasses conditions:	Excellent - no needs repair
◆ Lights conditions:	Broken or Chipped - needs repair
◆ Condizioni specchietti:	Rotto o Scheggiato - necessita riparazione
◆ Stepladders & handrails conditions:	Good
◆ Cameras conditions:	Excellent - no needs repair
◆ Flashing conditions:	Not functioning
◆ Safety belt conditions:	Present and valid

◆ Controls been modified:	No
◆ Presence of Exclusion Control Lever:	Yes
◆ Are Tools Functional & Visible with tag:	Yes
◆ Canopy completed and comes with keys and bolt:	Yes
◆ All Pipes with no damage e/o scratches:	Yes
◆ Batteries box shielded:	No
◆ Acoustic alarm works properly:	Yes
◆ Boardwalk presence:	Present and bashee

## Valutazione Macchina

### ★ Non Funzionante (NF)

La macchina si presenta non funzionante e/o in pessime condizioni. Macchina da demolire o venduta per parti di ricambio. La macchina NON è in sicurezza.

### ★★ Scarso (S)

La macchina è in cattivo stato e può presentare visibili rotture e/o crepe su tutta la struttura. Per il suo ottimale funzionamento, o per essere avviata, può necessitare di importanti riparazioni a carro/gomme, perdite d'olio, riverniciatura completa, componenti principali, messa in sicurezza.

### ★★★ Buono (B)

La macchina si presenta in buone condizioni sia estetiche che di funzionamento. Carro/Gomme hanno orientativamente un 30/40% di vita residua. La macchina non presenta importanti rotture e/o perdite d'olio. La macchina è pronta per lavorare "AS IS" anche se potrebbe richiedere piccoli interventi di riparazione/migliorie. La macchina è in sicurezza.

### ★★★★ Molto Buono (O)

La macchina si presenta in condizioni molto buone, non ha più di 5 anni e/o 5000 ore lavorate. Non presenta problemi strutturali e può essere preparata esteticamente per renderla "quasi nuova". Componenti principali non inferiori al 50/60% di vita residua, macchina in sicurezza.

### ★★★★★ Eccellente (E)

La macchina si presenta in condizioni eccellenti, prossime al nuovo. Componenti principali non inferiori al 70/80% di vita residua, macchina in sicurezza.

## Machine Rating

### ★ Not Working (NW)

Machine not operational or in really bad conditions. Machine has to be demolished or sold as a "parts". Machine not in security conditions.

### ★★ Poor (P)

Machine in bad condition, got visible cracks or repairable structural issues. Machine is operational but, in order to work properly, it may need significant repairs to tyres/truck, paint, pins and/or bushings, power train, hydraulic system.

### ★★★ Good (G)

Machine is in good condition and operational, with no structural issues. Tyres/Track around 30/40% of residual life. No relevant hydraulic leaks, pins/bushings with normal wear, frame may need to be repainted. Machine is ready to work "AS IS", it may need minor repairs for a better performance. Machine in security conditions or easy to be in safety condition.

### ★★★★ Very Good (VG)

Machine is in very good conditions, with no more of 5 years and/or 5000 working hours. No structural issues; painting condition is almost perfect. May need an easy check to be sold as "Brand New". Main components with 50/60% of life residue. Machine in security conditions.

### ★★★★★ Excellent (E)

Machine is in excellent condition, comparable to a new one. Main components-with 70/80% of life residue. Machine in security conditions.